



report date: 2024-03-29

General information

Make	FORD
Model	KA TITANIUM
Colour	Blue
Year of manufacture	2015
Top speed	99 mph
0 - 100 km/h	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	51 kW / 69 HP / 68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	115 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-09-30
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-09-29
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	13
Total items failed	11

MOT #10	2023-08-31 14:53
MOT test number	274078684950
Result	✓ Passed
Next expiry date	2024-09-29
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Rear axle is corroded

**MOT #9** 2023-08-31 08:10**MOT test number** 198360850886**Result** ✗ Failed**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Rear axle is corroded**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**MOT #8** 2022-09-30 14:25**MOT test number** 823465732877**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #7** 2022-09-28 15:07**MOT test number** 125493136057**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 1.6mm bald inner edge (5.2.3 (e))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #6** 2021-09-10 09:29**MOT test number** 774267027686**Result** ✓ Passed**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #5** 2021-09-09 10:29**MOT test number** 490174761708**Result** ✗ Failed**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #4** 2020-09-07 15:49**MOT test number** 320808648117**Result** ✓ Passed**MOT #3** 2019-09-21 10:13**MOT test number** 248937550913**Result** ✓ Passed



MOT #2	2018-09-25 11:49
MOT test number	393305045299
Result	✓ Passed

MOT #1	2018-09-25 10:44
MOT test number	538648707826
Result	✗ Failed

Fail Offside Front Windscreen wiper does not clear the windscreen effectively split (3.4 (b) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
29 September 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	29 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-09-25
Last registration	2023-08-31
Complete history	See info



Registration #1	2015-09-25	27 mi
Registration #2	2018-09-25	13.113 mi
Registration #3	2018-09-25	13.113 mi
Registration #4	2019-09-21	16.842 mi
Registration #5	2020-09-07	19.109 mi
Registration #6	2021-09-09	22.482 mi
Registration #7	2023-08-31	25.277 mi
Registration #8	2023-08-31	25.277 mi
Registration #9	2023-08-31	25.277 mi
Registration #10	2023-08-31	25.277 mi
Registration #11	2023-08-31	25.277 mi
Registration #12	2023-08-31	25.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	840 kg

Additional information

Fuel tank capacity	35 l
Number of axles	2
Engine number	1361424