



report date: 2024-03-29

General information

Make	FORD
Model	MONDEO TITANIUM X TDCI 140
Colour	Grey
Year of manufacture	2009
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-04
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-26
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	27
Total items failed	6

MOT #17	2023-09-27 14:41
MOT test number	135365254329
Result	✓ Passed
Next expiry date	2024-09-26
Advice	Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #16	2022-09-26 14:40
MOT test number	761056310269
Result	✓ Passed
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Underside slight corrosion
Advice	Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

**MOT #15** 2021-09-17 08:27**MOT test number** 766426715017**Result** ✓ Passed**MOT #14** 2021-09-17 08:27**MOT test number** 976298001473**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**MOT #13** 2020-09-26 08:29**MOT test number** 520184470614**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**MOT #12** 2020-09-26 08:29**MOT test number** 311797543374**Result** ✗ Failed**Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MOT #11** 2019-09-20 14:53**MOT test number** 767549656010**Result** ✓ Passed**MOT #10** 2019-09-20 14:53**MOT test number** 992605162408**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**MOT #9** 2018-09-18 11:50**MOT test number** 482568135440**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge on edges (5.2.3 (e))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm body mounting bush - just acceptable (5.3.4 (a) (i))**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**MOT #8** 2018-09-18 09:08**MOT test number** 856588894801**Result** ✗ Failed**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm body mounting bush - just acceptable (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge on edges (5.2.3 (e))**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**MOT #7** 2017-09-18 09:27**MOT test number** 487901942347**Result** ✓ Passed



MOT #6	2016-08-23 10:01
---------------	------------------

MOT test number	378392664503
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2015-09-01 00:00
---------------	------------------

MOT test number	723443618862
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2014-09-09 11:09
---------------	------------------

MOT test number	939202154236
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2013-09-09 12:36
---------------	------------------

MOT test number	317452353429
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2013-09-09 12:36
---------------	------------------

MOT test number	636462253285
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)
--------------------------------	---

MOT #1	2012-09-18 12:11
---------------	------------------

MOT test number	759262162295
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	---

Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
26 September 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	26 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-21
Last registration	2023-09-27
Complete history	See info



Registration #1	2009-09-21	8 mi
Registration #2	2012-09-18	28.263 mi
Registration #3	2013-09-09	38.583 mi
Registration #4	2014-09-09	46.823 mi
Registration #5	2015-09-01	53.199 mi
Registration #6	2016-08-23	61.192 mi
Registration #7	2017-09-18	66.129 mi
Registration #8	2018-09-18	71.608 mi
Registration #9	2018-09-18	71.612 mi
Registration #10	2019-09-18	76.129 mi
Registration #11	2019-09-18	76.129 mi
Registration #12	2019-09-18	76.129 mi
Registration #13	2019-09-18	76.129 mi
Registration #14	2019-09-18	76.129 mi
Registration #15	2019-09-18	76.129 mi
Registration #16	2019-09-18	76.129 mi
Registration #17	2019-09-18	76.129 mi
Registration #18	2019-09-18	76.129 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

9B03425