





General information

Make	MAZDA
Model	6 D TS
Colour	Grey
Year of manufacture	2009
Top speed	121 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	310 Nm at 1.800 rpm
Engine capacity	2.184 сс
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	147 g/km
CO2 label	F





MOT history

MOT expiry date	2021-10-05
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	17
Total items failed	9

MOT #13	2020-09-24 17:40
MOT test number	710559930609
Result	✓ Passed
Next expiry date	2021-10-05
AdviceNearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))AdviceOil leak	

MOT #12	2019-04-03 11:50
MOT test	number 263599691194
Result	✓ Passed
Advice	All steering & suspension components corroded
Advice	Oil leak, but not excessive unable to fully inspect due to covers & shields fitted (8.4.1 (a) (i))

MOT #11	2019-04-02 15:45
MOT test number	801707632880
Result	× Failed
Advice Oil leak, but not excessive unable to fully inspect due to covers & shields f	itted (8.4.1 (a) (i))
Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its s	structure (5.2.3 (d) (ii))
Fail Central Rear Seat belt missing (7.1.2 (a))	
Advice All steering & suspension components corroded	





MOT #10	2018-04-06 10:20
MOT test number	769335799408
Result	✓ Passed
Advice Nearside front tyre damage on outer wall close to cords	
MOT #9	2018-04-06 10:20
MOT test number	703388349535
Result	🗙 Failed
Advice Nearside front tyre damage on outer wall close to cords	
Pass with rectification Offside Registration plate lamp insecure (1.1.C.1c)	

MOT #8		2017-03-31 11:02
MOT test	number	657217551388
Result		✓ Passed
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #7	2017-03-31 11:02
MOT test number	871662831880
Result	🗙 Failed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Pass with rectificationOffside Front Front position lamp(s) not working (1.1.A.3b)	



EN59DVG report date: 2024-03-29

MOT #6	2016-04-02 13:20
MOT test number	137630915229
Result	✓ Passed
Advice Dpf light on	
MOT #5	2015-01-13 11:03
MOT test number	709523315069
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (3.5.1g)	
MOT #4	2014-12-30 16:19
MOT test number	549544464353
Result	× Failed
Fail Emissions not tested (7.4.B.1)	
Fail Service brake: efficiency below requirements (3.7.B.7)	
Notice Items not tested due to engine noisy and could cause damage to engine	
FailBrake performance not tested (3.7.A.1)	

МОТ #3	2013-12-17 17:02
MOT test number	916101153322
Result	✓ Passed

MOT #2	2013-12-17 17:02
MOT test number	716261653328
Result	× Failed
Pass with rectification	Offside Front Tyre has a cut in excess of the requirements deep enough to reach
the ply or cords (4.1.D.1a)	





MOT #1	2012-12-21 16:48
MOT test number	876966152318
Result	✓ Passed



Tax & MOT check

X Untaxed Tax expired: 1 April 2021	X MOT Expired: 5 October 2021
Tax status	Expired at 1 April 2021
Days left	1125 days too late
MOT expiry date	5 October 2021
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. ARANPE
Туре	
Damage 2	AMPL
Damage 2	E CUT-S
Date	14 N
Category	AMP
Туре	

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

NUMBER OF CONTRACTOR OF CONTRA	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



EN59DVG report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2009-12-31
Last registration	2020-09-24
Complete history	See info



Registration #1	2009-12-31	8 mi
Registration #2	2012-12-21	28.919 mi
Registration #3	2013-12-17	39.324 mi
Registration #4	2014-12-30	52.165 mi
Registration #5	2015-01-13	52.354 mi
Registration #6	2016-04-02	56.446 mi
Registration #7	2017-03-31	64.089 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		11.777 esi





Safety ratings

NCAP rating	****
Adult	77%
Children	81%
Pedestrian	49%
Safety systems	71%
Overall rating	72%
Video	see crash video



Dimensions & weight	
Width	1795 mm
Height	1440 mm
Length	4755 mm
Wheel base	2725 mm
Kerb weight	1560 kg
Max. allowed weight	2100 kg
Additional information	
Additional information Fuel tank capacity	64 I
	64 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5