





report date: 2024-03-28

General information

| Make | NISSAN |
|---------------------|-------------------|
| Model | LEAF ACENTA |
| Colour | White |
| Year of manufacture | 2016 |
| Top speed | 87 mph |
| Gearbox | 1 speed automatic |

Engine & fuel consumption

| Power | 107 BHP |
|-------------|----------------------|
| Max. torque | 254 Nm at 10.500 rpm |
| Fuel type | Electricity |



CarCheck.co.uk page 1/12



Internet history

| _ | | • | | _ | - |
|---|---|---|----|---|---|
| - | n | т | rv | , | |
| | | | | | |

| ciitiy 1 | |
|---------------|-------------|
| Date | 2021-09-29 |
| Pictures | 0 |
| Listing price | View report |

source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date | 2025-03-18 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 6 |
| Failed MOT tests | 2 |
| Total advice items | 17 |
| Total items failed | 5 |

| MOT #8 | | 2024-02-23 10:57 |
|-----------|--|------------------|
| MOT test | number | 597409622408 |
| Result | | ✓ Passed |
| Next expi | ry date | 2025-03-18 |
| Advice | Nearside Rear Service brake binding but not excessively (1.2.1 (f)) | |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a | a) (ii)) |
| Advice | Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i)) | |
| Advice | Child Seat fitted not allowing full inspection of adult belt | |

| MOT #7 | | 2024-02-23 10:57 |
|-----------------------------|---|------------------|
| MOT test number | | 466020515869 |
| Result | | × Failed |
| Advice Child Seat fitte | ed not allowing full inspection of adult belt | |
| Pass with rectification | Nearside Headlamp not working on dipped beam (4.1.1 (a) (i | i)) |
| Advice Nearside From | t Suspension arm ball joint has slight play (5.3.4 (a) (i)) | |
| Advice Nearside Rear | Service brake binding but not excessively (1.2.1 (f)) | |
| Advice Front Brake di | sc worn, pitted or scored, but not seriously weakened (1.1.14 (a) | (ii)) |

CarCheck.co.uk page 3/12



report date: 2024-03-28

| MOT #6 | | 2023-03-15 14:14 |
|----------|---|------------------|
| MOT test | number | 241609681601 |
| Result | | ✓ Passed |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #5 | 2022-03-11 12:36 |
|-------------------------------------|------------------|
| MOT test number | 108662128222 |
| Result | ✓ Passed |
| Advice Front and rear pads worn low | |

| MOT #4 | | 2021-03-09 14:09 |
|----------|---|------------------|
| MOT test | number | 956059098120 |
| Result | | ✓ Passed |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

CarCheck.co.uk page 4/12



MOT #3 2021-03-09 10:35

MOT test number 117939829715

Result × Failed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Nearside Headlamp aim too high (4.1.2 (a))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Rear fog lamp not working (4.5.1 (a) (ii))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #2 2020-03-17 11:48

MOT test number 889894050157

Result ✓ Passed

MOT #1 2019-03-15 11:25

MOT test number 811285164996

Result \rightarrow Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Days left 338
MOT expiry date 18 March 2025

Full MOT history See MOT history

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

| Owner | historv |
|-------|---|
| OWNER | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, |

| For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full is | |
|---|-------------|
| | |
| | |
| | |
| ************************************** | |
| | |
| | |
| | |
| ************************************** | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this NISSAN had different number plates. | |
| Number of plates | |
| Current registration | NK NK |
| Plate since | |
| Current registration | NK NK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 10 |
| First mileage registration | 2016-03-19 |
| Last registration | 2024-02-23 |
| Complete history | See info |



| Registration #1 | 2016-03-19 | 20 mi |
|---------------------------------|------------|----------------------------------|
| Registration #2 | 2019-03-15 | 54.227 mi |
| Registration #3 | 2020-03-17 | 70.101 mi |
| Registration #4 | 2021-03-09 | 78.470 mi |
| Registration #5 | 2021-03-09 | 78.470 mi |
| | | |
| Registration #6 | | 11.777 ea |
| | | 11.777 ea 11.777 ea |
| Registration #6 | | 11.77 m |
| Registration #6 Registration #7 | | 11.77 es 11.77 es 11.77 es |

More info >

CarCheck.co.uk page 11/12



Car features

| 0225 | Air conditionin |
|------|-----------------|
| 0295 | |
| 0482 | |
| 0501 | |
| 0566 | |
| 0567 | |
| 0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 89% |
| Children | 83% |
| Pedestrian | 65% |
| Safety systems | 84% |
| Overall rating | 83% |
| Video | see crash video |



Dimensions & weight

| Width | 1770 mm |
|---------------------|---------|
| Height | 1550 mm |
| Length | 4445 mm |
| Wheel base | 2700 mm |
| Kerb weight | 1538 kg |
| Max. allowed weight | 1945 kg |

Additional information

| Fuel delivery | Not Applicable |
|-----------------------------------|----------------|
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles CarCheck.co.uk | 2 page 12/12 |