





### General information

Make	BMW
Model	X5 XDRIVE30D M SPORT
Colour	White
Year of manufacture	2011
Top speed	138 mph
Gearbox	8 speed automatic

# Engine & fuel consumption

Power	241 BHP	0 < 101 A
Max. torque	540 Nm at 1.750 rpm	101 - 120 <sup>B</sup> <sub>C</sub>
Engine capacity	2.993 сс	121 - 140 F
Cylinders	6	141 - 165 F G
Fuel type	Diesel	166 - 185 H
Consumption city	32.5 mpg	186 - 225
Consumption extra urban	42.2 mpg	225+
Consumption combined	38.2 mpg	
CO2 emission	195 g/km	
CO2 label	J	





Internet history		
Entry 1		
Date	2021-01-29	
Pictures	1	
Listing price	View report	



source: autoonline.co.uk



# MOT history

MOT expiry date	2024-06-20
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	25
Total items failed	0

MOT #13		2023-05-24 12:23
MOT test	number	947491236959
Result		✓ Passed
Next exp	iry date	2024-06-20
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Minor	Nearside Front Lower Anti-roll bar ball joint dust cover severely deteriorated	d (5.3.4 (b) (i))
<b>Advice</b> (4.1.4 (b))	Front Headlamp has a product on the lens but not seriously reducing light	output BOTH SIDES
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2022-06-18 10:19
MOT test number	994719918650
Result	✓ Passed
Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #11	2021-06-21 10:40
MOT test number	488611423641
Result	✓ Passed
Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Tyre worn close to legal limit/worn on edge O S F and N S R (5.2.3 (e))	

МОТ #10	2021-06-19 16:41	
MOT test number	377068446830	
Result	🗙 Failed	
Advice Tyre worn close to legal limit/worn on edge O S F and N S R (5.2.3 (e))		
Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))		
<b>DANGEROUS</b> Road wheel more than one fixing missing One of each (5.2.1 (a) (ii))		

MOT #9		2020-12-10 10:46
MOT test	number	247228748923
Result		✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8	2019-12-09 14:03
MOT test number	977505644540
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	





MOT #7		2019-12-06 13:26
MOT test	number	370747615376
Result		🗙 Failed
<b>MAJOR</b> (5.2.3 (d)	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach t (i))	he ply or cords
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>MAJOR</b> (5.2.3 (d)	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach (i))	n the ply or cords
MOT #C		2010 10 22 14 42
MOT #6 MOT test	number	2018-10-23 14:43 597737892867
Result		✓ Passed
Result		
MOT #5		2017-10-26 11:53
MOT test	number	184643461757
Result		✓ Passed
Advice	Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Advice componer	Covers in engine bay and undertrays fitted obscuring and preventing inspection onts	of some

MOT #4	2016-10-08 09:12
MOT test number	304045066110
Result	✓ Passed

MOT #3	2015-11-03 17:14
MOT test number	421463407032
Result	✓ Passed





MOT #2		2014-11-05 15:36
MOT test	number	817809604337
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	

MOT #1	2014-09-25 13:00
MOT test number	557708164249
Result	✓ Passed



Tax & MOT check

Taxed	MOT Expires: 20 June 2024
Tax status	Valid until 1 July
Days left	64
MOT expiry date	20 June 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-





#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	e et al
Date	*
Category	AMP
Туре	

#### Extra BMW salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second sec	
*************	
********	
*******	
*************	
********	
	More info >
Plate changes	
See in this check if this BMW had different number plate	S.
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-10-20
Last registration	2023-05-24
Complete history	See info



Registration #1	2011-10-20	6 mi
Registration #2	2014-09-25	18.721 mi
Registration #3	2014-11-05	18.985 mi
Registration #4	2015-11-03	31.333 mi
Registration #5	2016-10-08	42.011 mi
Registration #6	2017-10-26	49.276 mi
Registration #7	2018-10-23	55.614 mi
Registration #8	2019-12-06	69.671 mi
Registration #9		11.777 mi
Registration #10		11.777 est
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 mi
Registration #15		11.777 mi





#### Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
S0566	
\$0567	
S0569	

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	1933 mm
Height	1776 mm
Length	4857 mm
Wheel base	2933 mm
Kerb weight	2075 kg
Max. allowed weight	2755 kg
Additional information	
Fuel tank capacity	85 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	32207728