



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA EXCLUSIVE 16V PICASSO
Colour	Green
Year of manufacture	2003
Top speed	118 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	117 BHP
Max. torque	162 Nm at 4.000 rpm
Engine capacity	1.749 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	36.7 mpg
CO2 emission	184 g/km
CO2 label	I






Internet history

Entry 1

Date	2022-01-06
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-12
MOT pass rate	78 %
MOT passed	18
Failed MOT tests	5
Total advice items	26
Total items failed	19

MOT #23 2023-08-09 08:36

MOT test number 323756323703

Result ✓ Passed

Next expiry date 2024-08-12

Advice Front Brake disc worn, pitted or scored, but not seriously weakened o/s and n/s (1.1.14 (a) (ii))

Advice Rear Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))

Advice Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MOT #22 2022-08-02 16:01

MOT test number 303668697060

Result ✓ Passed

Advice Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #21 2021-08-11 15:06

MOT test number 551223954877

Result ✓ Passed

Advice Power steering component has slight seepage from a component (2.1.5 (a))

Advice Oil leak, but not excessive Advise Repair (8.4.1 (a) (i))

**MOT #20**

2021-07-31 12:43

MOT test number

312809925193

Result**✗ Failed**

- Fail** Nearside Front Headlamp lens seriously defective (4.1.1 (b) (ii))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Oil leak, but not excessive Advise Repair (8.4.1 (a) (i))
- Fail** Offside Front Headlamp lens seriously defective (4.1.1 (b) (ii))
- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Power steering component has slight seepage from a component (2.1.5 (a))

MOT #19

2020-08-13 08:31

MOT test number

178065255311

Result**✓ Passed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #18

2020-08-12 10:55

MOT test number

347025833728

Result**✗ Failed**

- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- Fail** Offside Headlamp aim not tested (4.1.2 (b))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- Fail** Nearside Headlamp aim not tested (4.1.2 (b))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #17** 2019-10-26 07:33**MOT test number** 945792766403**Result** ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Minor** Headlamp lens slightly defective both (4.1.1 (b) (i))

MOT #16 2019-10-19 08:23**MOT test number** 974531217483**Result** ✗ Failed

- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Minor** Headlamp lens slightly defective both (4.1.1 (b) (i))
- Fail** Offside Side repeater incorrect colour (4.4.3 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Fail** Nearside Side repeater incorrect colour (4.4.3 (a))
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

MOT #15 2018-10-25 11:04**MOT test number** 217126083693**Result** ✓ Passed

**MOT #14** 2017-08-31 08:07**MOT test number** 529657304142**Result** ✓ Passed

- Advice** Nearside Side repeater slightly discoloured (1.4.A.2f)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Side repeater slightly discoloured (1.4.A.2f)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #13 2016-08-31 07:46**MOT test number** 922647195584**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Exhaust heatshield loose

MOT #12 2015-08-26 00:00**MOT test number** 307788463536**Result** ✓ Passed**MOT #11** 2014-09-18 15:53**MOT test number** 357191564403**Result** ✓ Passed

- Notice** Exhaust corroding

**MOT #10** 2014-09-18 15:53**MOT test number** 635311764235**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too far to the right (1.8)**Notice** Exhaust corroding**MOT #9** 2013-09-23 14:38**MOT test number** 509726563250**Result** ✓ Passed**MOT #8** 2012-08-31 09:44**MOT test number** 628444242299**Result** ✓ Passed**MOT #7** 2011-09-13 14:22**MOT test number** 629666551279**Result** ✓ Passed**Notice** Advise air bag light on**MOT #6** 2010-07-16 14:22**MOT test number** 813317190133**Result** ✓ Passed**MOT #5** 2009-07-20 16:06**MOT test number** 771761309216**Result** ✓ Passed



MOT #4	2009-07-20 16:06
MOT test number	114881809233
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)
Pass with rectification	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
Pass with rectification	Front brake disc in such a condition that it is seriously weakened (3.5.1i)

MOT #3	2008-07-16 10:48
MOT test number	663888798128
Result	✓ Passed

MOT #2	2007-07-18 13:21
MOT test number	112869097122
Result	✓ Passed

MOT #1	2006-07-20 16:56
MOT test number	781091906250
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
9 February 2024

✓

MOT

Expires:
12 August 2024

Tax status	Expired at 9 February 2024
Days left	81 days too late
MOT expiry date	12 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2003-07-30
Last registration	2023-08-09
Complete history	See info



Registration #1	2003-07-30	7 mi
Registration #2	2006-07-20	30.836 mi
Registration #3	2007-07-18	42.520 mi
Registration #4	2008-07-16	53.075 mi
Registration #5	2009-07-20	60.790 mi
Registration #6	2010-07-16	69.083 mi
Registration #7	2011-09-13	73.766 mi
Registration #8	2012-08-31	79.036 mi
Registration #9	2013-09-23	84.786 mi
Registration #10	2014-09-18	90.942 mi
Registration #11	2015-08-26	94.544 mi
Registration #12	2016-08-31	97.641 mi
Registration #13	2017-08-31	99.999 mi
Registration #14	2018-08-31	99.999 mi
Registration #15	2019-08-31	99.999 mi
Registration #16	2020-08-31	99.999 mi
Registration #17	2021-08-31	99.999 mi
Registration #18	2022-08-31	99.999 mi
Registration #19	2023-08-09	99.999 mi
Registration #20		
Registration #21		
Registration #22		
Registration #23		

More info >



Safety ratings

NCAP rating

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1752 mm
Height	1625 mm
Length	4267 mm
Wheel base	2760 mm
Kerb weight	1245 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	LT140773351