



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT FSI
Colour	Black
Year of manufacture	2006
Top speed	130 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	200 Nm at 3.500 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.0 mpg
CO2 emission	197 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-06-11
Pictures	17
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2022-01-05
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	23
Total items failed	1

MOT #14 2021-01-06 14:53

MOT test number 934796125149

Result ✓ Passed

Next expiry date 2022-01-05

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Windscreen cracked

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Oil leak

MOT #13 2020-01-02 11:37

MOT test number 244411511377

Result ✓ Passed

MOT #12 2020-01-02 11:37

MOT test number 376098373170

Result ✗ Failed

Pass with rectification Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #11 2018-12-21 12:27

MOT test number 706926278955

Result ✓ Passed

**MOT #10** 2017-12-27 11:42**MOT test number** 885442571914**Result** ✓ Passed**MOT #9** 2017-01-03 11:58**MOT test number** 408018713323**Result** ✓ Passed**MOT #8** 2015-12-10 11:49**MOT test number** 363381590402**Result** ✓ Passed**MOT #7** 2015-01-02 17:21**MOT test number** 397692505035**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Offside Front Lower Anti-roll bar ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Offside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #6** 2013-12-20 09:55**MOT test number** 579474253372**Result** ✓ Passed**Advice** Nearside Front Lower Radius arm has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Front Lower Radius arm has slight play in a pin/bush (2.4.G.2)**Advice** Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

**MOT #5** 2012-12-11 17:49**MOT test number** 677246042394**Result** ✓ Passed**MOT #4** 2012-01-26 13:20**MOT test number** 115166722498**Result** ✓ Passed

- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Upper Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2011-01-28 15:46**MOT test number** 737468221097**Result** ✓ Passed

- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

MOT #2 2010-01-27 15:13**MOT test number** 834807920014**Result** ✓ Passed



MOT #1	2009-01-28 09:29
MOT test number	281788329035
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
2 July 2021

X

MOT

Expired:
5 January 2022

Tax status	Expired at 2 July 2021
Days left	1033 days too late
MOT expiry date	5 January 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 KS55UWH
Plate since	2019-03-29
Current registration	 KS55UWH
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2006-01-28
Last registration	2021-01-06
Complete history	See info



Registration #1	2006-01-28	14 mi
Registration #2	2009-01-28	16.665 mi
Registration #3	2010-01-27	25.270 mi
Registration #4	2011-01-28	35.754 mi
Registration #5	2012-01-26	45.216 mi
Registration #6	2012-12-11	54.219 mi
Registration #7	2013-12-20	59.099 mi
Registration #8	2015-01-02	64.752 mi
Registration #9	2016-01-28	70.217 mi
Registration #10	2017-01-28	75.217 mi
Registration #11	2018-01-28	80.217 mi
Registration #12	2019-01-28	85.217 mi
Registration #13	2020-01-28	90.217 mi
Registration #14	2021-01-28	95.217 mi
Registration #15	2022-01-28	100.217 mi
Registration #16	2023-01-28	105.217 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Kerb weight	1481 kg
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Engine number	BVY 084246