



PEUGEOT




report date: 2024-03-28

General information

Make	PEUGEOT
Model	RCZ THP GT
Colour	Black
Year of manufacture	2010
Top speed	134 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	156 BHP
Max. torque	240 Nm at 1.400 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	54.3 mpg
Consumption combined	42.2 mpg
CO2 emission	155 g/km
CO2 label	G






Internet history

Entry 2

Date	2022-01-05
Pictures	5
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-07-07
Pictures	6
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2023-01-10
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	31
Total items failed	27

MOT #16	2022-01-11 08:58
MOT test number	619876529564
Result	✓ Passed
Next expiry date	2023-01-10

MOT #15	2021-07-01 07:31
MOT test number	259867241767
Result	✓ Passed

MOT #14	2020-07-14 14:32
MOT test number	649996170069
Result	✓ Passed



MOT #13	2020-06-11 14:04
MOT test number	275487021738
Result	✗ Failed
Advice	Fluid leak, but not excessive engine coolant (8.4.1 (a) (i))
Fail	Offside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Fail	Rear Exhaust system insecure (6.1.2 (a))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #12	2019-05-01 12:29
MOT test number	201933468888
Result	✓ Passed
Advice	Items removed from driver's view prior to test

MOT #11	2019-04-29 11:11
MOT test number	486498834868
Result	✗ Failed
Advice	Items removed from driver's view prior to test
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))
Fail	Offside Rear Service brake excessively fluctuating (1.2.1 (e))
Fail	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Nearside Rear Service brake excessively fluctuating (1.2.1 (e))

**MOT #10**

2018-05-01 07:54

**MOT test number**

293170531195

**Result**

✓ Passed

**Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement Near and Offside rear bushes (2.4.G.2)

**Advice** Exhaust flex section deteriorated

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened Near and Offside (3.5.1i)

**Advice** Engine light showing a fault

**MOT #9**

2018-04-17 15:41

**MOT test number**

318684557016

**Result**

✗ Failed

**Fail** Front Tyre fouling a part of the vehicle Near and Offside wheel arch body (4.1.D.2)

**Fail** Nearside rear brake excessively fluctuating A LOT (3.7.B.3)

**Advice** Engine light showing a fault

**Fail** Windscreen wiper does not clear the windscreen effectively Near and Offside floppy (8.2.2)

**Fail** Parking brake: efficiency below requirements (3.7.B.7)

**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened Near and Offside inner face heavily deteriorated (3.5.1i)

**Advice** Offside Front tyre had damage to outer side wall

**Fail** Nearside Front Tyre has ply or cords exposed outer side wall (4.1.D.1b)

**Fail** Nearside rear brake application uneven slow to react (3.7.B.2)

**Fail** Offside Registration plate lamp not working (1.1.C.1d)

**Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement Near and Offside rear bushes (2.4.G.2)

**Advice** Vehicles internal headlight adjuster altered to recheck lights

**Advice** Exhaust flex section deteriorated

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened Near and Offside (3.5.1i)

**MOT #8** 2017-04-19 15:20**MOT test number** 460210768361**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit Tyre wearing on inner edge. (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2017-04-19 12:38**MOT test number** 341568537453**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit Tyre wearing on inner edge. (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2016-07-29 13:25**MOT test number** 392983321976**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit 2.5mm (4.1.E.1)**Advice** Nsr tyre wall damaged/small cut**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2016-07-29 10:54**MOT test number** 958575355154**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit 2.5mm (4.1.E.1)**Advice** Nsr tyre wall damaged/small cut**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Nearside Registration plate lamp not illuminating the registration plate (1.1.C.1e)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #4** 2015-06-24 08:37**MOT test number** 769895575173**Result** ✓ Passed**MOT #3** 2014-07-01 18:01**MOT test number** 539352684182**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**Notice** Engine noisy during acceleration for emissions test



MOT #2	2014-07-01 12:59
MOT test number	128522484149
Result	✗ Failed
Fail	Nearside Stop lamp obscured more than 50% (1.2.1c)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Offside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)
Fail	Offside Rear position lamp(s) has a product on the lens so it is not visible from a reasonable distance (1.1.A.3d)
Notice	Engine noisy during acceleration for emissions test
Fail	Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Rear reflector excessively damaged so that its function is impaired (1.5.1c)
Notice	Nearside rear bumper/light cluster damaged,affecting light output

MOT #1	2013-07-02 14:54
MOT test number	969553983197
Result	✓ Passed





Tax & MOT check

X

Untaxed

Tax expired:  
1 March 2023

X

MOT

Expired:  
10 January 2023

Tax status	Expired at 1 March 2023
Days left	424 days too late
MOT expiry date	10 January 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>SH10UWY</b>
Plate since	2019-03-28
Current registration	<b>SH10UWY</b>
Plate since	2019-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-06-10
Last registration	2022-01-11
Complete history	<a href="#">See info</a>



Registration #1	2010-06-10	10 mi
Registration #2	2013-07-02	18.191 mi
Registration #3	2014-07-01	30.929 mi
Registration #4	2014-07-01	30.929 mi
Registration #5	2015-06-24	43.371 mi
Registration #6	2016-07-29	50.611 mi
Registration #7	2016-07-29	50.611 mi
Registration #8	2017-04-19	53.457 mi
Registration #9	2017-04-19	53.462 mi
Registration #10	2018-04-17	56.937 mi
Registration #11	2019-04-17	59.371 mi
Registration #12	2019-04-17	59.371 mi
Registration #13	2019-04-17	59.371 mi
Registration #14	2019-04-17	59.371 mi
Registration #15	2019-04-17	59.371 mi
Registration #16	2019-04-17	59.371 mi
Registration #17	2019-04-17	59.371 mi
Registration #18	2019-04-17	59.371 mi
Registration #19	2019-04-17	59.371 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	82%
Children	81%
Pedestrian	53%
Safety systems	83%
Overall rating	76%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2107 mm
Height	1352 mm
Length	4290 mm
Wheel base	2612 mm
Kerb weight	1350 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	FJBD0814353