





report date: 2024-03-29

#### General information

Make	PEUGEOT
Model	206 S
Colour	Silver
Year of manufacture	2003
Top speed	108 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	74 BHP
Max. torque	120 Nm at 3.400 rpm
Engine capacity	1.360 сс
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.1 mpg
CO2 emission	153 g/km
CO2 label	G



CarCheck.co.uk page 1/15



## Internet history

#### Entry 1

Date 2021-06-21

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2024-07-17
MOT pass rate	82 %
MOT passed	18
Failed MOT tests	4
Total advice items	26
Total items failed	13

MOT #22	2023-07-12 09:26
MOT test number	879986865183
Result	✓ Passed
Next expiry date	2024-07-17
Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))	
Minor Rear Registration plate lamp inoperative in the case of multiple lamps of	or light sources (4.7.1 (b) (i))

MOT #21		2022-07-18 16:02
MOT test	number	636175186328
Result		✓ Passed
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/15



Advice

LV53LRK report date: 2024-03-29

MOT test number

402919821934

Result

Pass with rectification

Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice

Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #19 2021-05-18 16:40 **MOT test number** 259122932292 Result ✓ Passed 2020-04-18 08:02 **MOT #18 MOT** test number 549497617091 Result ✓ Passed **MOT #17** 2019-05-17 10:54 **MOT** test number 785071892449 Result ✓ Passed **Advice** Nearside Rear Bump stop is missing **Advice** Oil leak, but not excessive (8.4.1 (a) (i))

CarCheck.co.uk page 4/15



**MOT #16** 2019-05-15 13:18

**MOT test number** 914085927834

Result X Failed

Fail Front Windscreen washer not working (3.5 (a))

Fail Exhaust has a major leak of exhaust gases catalytic converter is cracked (6.1.2 (a))

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail All direction indicators not working Intermittently working with the headlights on (4.4.1 (a) (ii))

**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits catalytic converter is cracked (8.2.1.2 (c))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Nearside Rear Bump stop is missing

**Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt Steering rack gaiter is insecure (2.1.3 (g) (ii))

**MOT #15** 2018-04-30 08:05

**MOT test number** 336726646917

**Result** 
✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit On limit (4.1.E.1)

**MOT #14** 2018-04-30 08:05

**MOT test number** 250935588971

**Result** X Failed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

(1.1.A.3b)

Pass with rectification Offside Front position lamp(s) has less than 50% of the light sources illuminating

**Advice** Offside Front Tyre worn close to the legal limit On limit (4.1.E.1)

**Pass with rectification** Offside Side repeater incorrect colour (1.4.A.2f)

CarCheck.co.uk page 5/15



**X** Failed

MOT #13 2017-04-24 08:11 MOT test number 497776823395

**Result** ✓ Passed

Advice

Result

Nearside rear tyre cracking

MOT #12 2017-04-24 08:11

**MOT test number** 414532497492

Pass with rectification Nearside Rear Registration plate lamp not working (1.1.C.1d)

Nearside Stop lamp not working (1.2.1b)

Pass with rectification Nearside Headlamp not working on dipped beam (1.7.5a)

**Advice** Nearside rear tyre cracking

Pass with rectification

**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)

**MOT #11** 2016-05-09 08:03

**MOT test number** 432084265590

Result Passed

Advice

Small cracks in n/s rear tyre sidewall

**MOT #10** 2015-05-11 13:44

**MOT test number** 457081735121

**Result** ✓ Passed

MOT #9 2014-05-12 10:17

**MOT test number** 267002834466

**Result** 
✓ Passed

CarCheck.co.uk page 6/15



MOT #8 2013-05-08 14:09 **MOT test number** 807298023179 Result ✓ Passed 2012-05-04 08:04 MOT #7 **MOT test number** 185225022193 Result ✓ Passed **Notice** Slight play in offside steering rack-end Notice Noise from engine area (clutch release bearing?) Notice Front brake pads same thickness as the pad metal Notice Slight play found in nearside steering rack-end (minute).

MOT #6	2011-05-09 12:29
MOT test number	157679821130
Result	<b>✓</b> Passed
MOT #5	2010-05-14 15:27
MOT test number	253184830497
Result	<b>✓</b> Passed
MOT #4	2009-05-13 13:03
MOT test number	760133539148
Result	✓ Passed
MOT #3	2008-09-16 15:43
MOT test number	173510968286
Result	<b>✓</b> Passed
Notice Nail in offside rear tyre	

CarCheck.co.uk page 7/15



 MOT #2
 2007-09-05 15:27

 MOT test number
 570168547210

 Result
 ✓ Passed

 MOT #1
 2006-09-20 13:08

 MOT test number
 340443666251

 Result
 ✓ Passed

 Advice
 Offside Front wheel bearing has slight play (2.5.A.3c)

CarCheck.co.uk page 8/15



#### Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	17 July 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 9/15



#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



Owner	history
O WILCI	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,

Owner history	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
***************************************	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	ZIS UK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 12/15



#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

**Contact info** 


More info >

CarCheck.co.uk page 13/15



## Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-09-24
Last registration	2023-07-12
Complete history	See info



Registration #1	2003-09-24	25 mi
Registration #2	2006-09-20	12.869 mi
Registration #3	2007-09-05	14.894 mi
Registration #4	2008-09-16	16.853 mi
Registration #5	2009-05-13	17.359 mi
Registration #6	2010-05-14	25.928 mi
Registration #7	2011-05-09	35.898 mi
Registration #8	2012-05-04	44.158 mi
Registration #9	2013-05-08	54.155 mi
Registration #10	2014-05-12	61.641 mi
Registration #11	2015-05-11	71.612 mi
Registration #12	2016-05-09	80.217 mi
Registration #13		71.777 es
Registration #13 Registration #14		11.777 ea
		11,777 ea 11,777 ea 11,777 ea
Registration #14		11,777 ea 11,777 ea 11,777 ea
Registration #14 Registration #15		11,777 ea 11,777 ea 11,777 ea 11,777 ea
Registration #14 Registration #15 Registration #16		11,777 ea 11,777 ea 11,777 ea 11,777 ea
Registration #14 Registration #15 Registration #16 Registration #17		11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18		11,777 es 11,777 es 11,777 es 11,777 es 11,777 es 11,777 es
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		11,777 est
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		11,777 est
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea

More info >



### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1673 mm
Height	1460 mm
Length	4028 mm
Wheel base	2442 mm
Kerb weight	1074 kg

# Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number CarCheck.co.uk	FSM74583038 page 15/15