



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO ACTIVE
Colour	White
Year of manufacture	2010
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-07-17
Pictures	44
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-11
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	42
Total items failed	6

MOT #14	2023-07-10 08:28
MOT test number	897640016638
Result	✓ Passed
Next expiry date	2024-07-11
Advice	Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #13	2023-07-10 08:28
MOT test number	206956103024
Result	✗ Failed
Advice	Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #12**

2022-07-09 14:40

MOT test number

438730316706

Result

✓ Passed

Advice

Front Brake Disc Rusty

MOT #11

2022-07-08 15:10

MOT test number

983328184729

Result

✗ Failed

Fail

Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice

Front Brake Disc Rusty

Fail

Nearside Front Direction indicator incorrect colour (4.4.3 (a))

Fail

Rear Direction indicator incorrect colour Both (4.4.3 (a))

MOT #10

2021-07-12 14:56

MOT test number

175635004298

Result

✓ Passed

Advice

Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #9

2020-12-05 09:34

MOT test number

487318658385

Result

✓ Passed

Advice

Rear Shock absorbers has slight external damage to the casing both ns & os (5.3.2 (b))

Advice

Nearside Front drive shaft oil seal slight leak

Advice

Offside Front Play in steering rack inner joint(s)

Advice

Rear Lower Coil spring corroded both ns & os (5.3.1 (b) (i))

**MOT #8**

2020-12-05 09:34

MOT test number

696564701912

Result**✗ Failed**

- Advice** Nearside Front drive shaft oil seal slight leak
- Advice** Rear Shock absorbers has slight external damage to the casing both ns & os (5.3.2 (b))
- Advice** Offside Front Play in steering rack inner joint(s)
- Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))
- Advice** Rear Lower Coil spring corroded both ns & os (5.3.1 (b) (i))

MOT #7

2019-12-07 09:36

MOT test number

263765844948

Result**✓ Passed**

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front drive shaft oil seal slight leak
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Exhaust back box outer skin corroded
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Coolant stain on timing cover side no drips



MOT #6	2018-12-15 08:51
MOT test number	788016028406
Result	✓ Passed
Advice	Nearside driveshaft seal looks like it starting to leak
Advice	Both rear shocker casings corroded
Advice	Exhaust back box corroded
Advice	Both rear springs corroded
Advice	Both front brake disc's looking worn

MOT #5	2017-12-16 11:19
MOT test number	582171652906
Result	✓ Passed
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Back box outer skin corroded
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Slight oil leak

**MOT #4** 2016-12-05 16:28**MOT test number** 862636163513**Result** ✓ Passed

- Advice** Offside Front coil spring corroded (2.4.C.1b)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front coil spring corroded (2.4.C.1b)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)
- Advice** Exhaust back box corroded
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3 2015-12-07 15:26**MOT test number** 786959231567**Result** ✓ Passed**MOT #2** 2014-12-06 09:35**MOT test number** 588920644347**Result** ✓ Passed**MOT #1** 2013-12-07 10:19**MOT test number** 666831043337**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
11 July 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	11 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-12-29
Last registration	2023-07-10
Complete history	See info



Registration #1	2010-12-29	11 mi
Registration #2	2013-12-07	21.338 mi
Registration #3	2014-12-06	27.810 mi
Registration #4	2015-12-07	33.474 mi
Registration #5	2016-12-05	39.123 mi
Registration #6	2017-12-16	45.413 mi
Registration #7	2018-12-15	51.001 mi
Registration #8	2019-12-07	57.195 mi
Registration #9	2020-06-29	63.389 mi
Registration #10	2021-06-29	69.583 mi
Registration #11	2022-06-29	75.777 mi
Registration #12	2023-06-29	81.971 mi
Registration #13	2023-06-29	88.165 mi
Registration #14	2023-06-29	94.359 mi
Registration #15	2023-06-29	100.553 mi
Registration #16	2023-06-29	106.747 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	5839116