





report date: 2024-03-28

### General information

Make	VOLKSWAGEN
Model	CC GT TDI BLUEMOTION TECHNOLOGY
Colour	Grey
Year of manufacture	2012
Top speed	133 mph
0 - 100 km/h	9.8 seconds
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg
CO2 emission	120 g/km
CO2 label	С



CarCheck.co.uk page 1/10



# Internet history

### Entry 1

Date 2021-12-11

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/10



MOT history

MOTHIStory	
MOT expiry date	2024-11-27
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	2
Total items failed	4
MOT #11	2023-11-20 10:04
MOT test number	847104808949
Result	✓ Passed
Next expiry date	2024-11-27
next expiry date	20211127
MOT #10	2022-11-15 14:22
MOT test number	742840220241
Result	<b>✓</b> Passed
MOT #9	2021-11-15 14:30
MOT test number	989176903217
Result	<b>✓</b> Passed
MOT #8	2020-11-26 18:38
MOT test number	342957777658
Result	✓ Passed
	•
MOT #7	2019-11-11 10:19
MOT test number	321556622189
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/10



MOT #6 2018-10-31 12:09

**MOT test number** 561802016364

**Result** 
✓ Passed

MOT #5 2018-10-24 15:00

**MOT test number** 875100012723

Result × Failed

Fail Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))

MOT #4 2017-11-10 08:37

**MOT test number** 847950716018

**Result** ✓ Passed

MOT #3 2017-11-09 16:01

**MOT test number** 295984352371

Result X Failed

**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)

**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #2 2016-11-15 10:52

**MOT test number** 563339626113

**Result** ✓ Passed

**MOT #1** 2015-11-28 08:56

MOT test number 941021609192

Result 

Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/10




#### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra VOLKSWAGEN salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



More info >

### Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Downere.	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	OK OK
Plate since	

CarCheck.co.uk page 7/10



#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 8/10



# Mileage check

Odometer	In kilometers
Mileage registrations	13
First mileage registration	2012-11-28
Last registration	2023-11-20
Complete history	See info



Registration #1	2012-11-28	14 mi
Registration #2	2015-11-28	61.094 mi
Registration #3	2016-11-15	75.610 mi
Registration #4	2017-11-09	91.357 mi
Registration #5	2017-11-10	91.357 mi
Registration #6	2018-10-24	94.055 mi
Registration #7	2018-10-31	94.058 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 es
Registration #12		11.777 es
Registration #13		70.777 au

More info >

CarCheck.co.uk page 9/10



### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	see crash video



# Dimensions & weight

Width	2090 mm
Height	1421 mm
Length	4902 mm
Wheel base	2710 mm
Kerb weight	1550 kg
Max. allowed weight	2050 kg

### Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
CarChock co.uk	page 10/10

CarCheck.co.uk page 10/10

Number of axles	2
Engine number	CFFBD24555