




report date: 2024-03-28

General information

Make	VOLVO
Model	XC90 SE AWD
Colour	Blue
Year of manufacture	2007
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	235 BHP
Max. torque	320 Nm at 3.200 rpm
Engine capacity	3.192 cc
Cylinders	6
Fuel type	Petrol
Consumption city	16.4 mpg
Consumption extra urban	30.7 mpg
Consumption combined	23.3 mpg
CO2 emission	281 g/km
CO2 label	M





Internet history

Entry 2



Date	2023-12-09
Pictures	7
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-12-07
MOT pass rate	61 %
MOT passed	14
Failed MOT tests	9
Total advice items	45
Total items failed	24

MOT #23	2023-12-08 17:46
MOT test number	345532740698
Result	✓ Passed
Next expiry date	2024-12-07

MOT #22	2023-02-20 08:58
MOT test number	163245254802
Result	✓ Passed
Advice	Gearbox mounting defective
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Bush (5.3.4 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Bush (5.3.4 (a) (i))

**MOT #21**

2023-02-18 10:54

MOT test number

968568055596

Result**✗ Failed****Advice**

Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Bush (5.3.4 (a) (i))

Fail

Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Gearbox mounting defective

Advice

Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Bush (5.3.4 (a) (i))

MOT #20

2022-02-01 14:06

MOT test number

935149543384

Result**✓ Passed****Advice**

Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

MOT #19

2022-02-01 09:27

MOT test number

729882969246

Result**✗ Failed****Advice**

Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

Fail

Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #18

2021-01-08 16:15

MOT test number

609014199102

Result**✓ Passed**



MOT #17	2021-01-06 11:51
MOT test number	755749171510
Result	✗ Failed
Fail	Brake pad(s) less than 1.5 mm thick Both rear (1.1.13 (a) (ii))
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #16	2019-11-16 10:12
MOT test number	924799383372
Result	✓ Passed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone rear mount deteriorated but not excessive movement (5.3.4 (a) (i))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Exhaust front hangers are broken , but system is still secure.

MOT #15	2019-11-15 17:48
MOT test number	905492727920
Result	✗ Failed
Fail	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone rear mount deteriorated but not excessive movement (5.3.4 (a) (i))
Fail	Nearside Front Position lamp not working both of them (4.2.1 (a) (ii))
Fail	Electronic stability control warning lamp indicates a fault (7.12 (e))
Fail	Offside Front Suspension arm pin or bush excessively worn wishbone rear mount (5.3.4 (a) (i))
Fail	Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Exhaust front hangers are broken , but system is still secure.
Fail	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

**MOT #14** 2018-11-01 12:08**MOT test number** 663315070010**Result** ✓ Passed**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #13** 2018-11-01 10:02**MOT test number** 864725653714**Result** ✗ Failed**Fail** Fuel cap/sealing device ineffective rubber seal split in half (6.1.3 (b) (i))**Fail** Offside Front Headlamp aim too low (4.1.2 (a))**Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #12** 2017-10-18 16:43**MOT test number** 194672381430**Result** ✓ Passed**Advice** Both front tyres are wearing**MOT #11** 2017-10-16 16:20**MOT test number** 393892143837**Result** ✗ Failed**Fail** Power steering fluid level below minimum (2.3.1)**Fail** Power steering component(s) leaking from a failed seal (2.3.3b)**Advice** Both front tyres are wearing**Fail** Offside Rear fog lamp not working (1.3.2b)

**MOT #10** 2017-02-01 12:55**MOT test number** 264603487758**Result** ✓ Passed

- Advice** Parking brake not working- repaired PRS
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened inner surfaces (3.5.1i)
- Advice** Offside Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)
- Advice** Nearside Front suspension has slight play in a pin or bush of an lower wishbone inner bearing (2.5.B.1a)

MOT #9 2017-02-01 12:55**MOT test number** 359277872699**Result** ✗ Failed

- Advice** Offside Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened inner surfaces (3.5.1i)
- Advice** Nearside Front suspension has slight play in a pin or bush of an lower wishbone inner bearing (2.5.B.1a)
- Advice** Parking brake not working- repaired PRS
- Pass with rectification** Offside Front All position lamps not working (1.1.A.3b)
- Pass with rectification** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Pass with rectification** Offside Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)

**MOT #8** 2016-02-23 17:33**MOT test number** 142161407242**Result** ✓ Passed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)

MOT #7 2016-02-23 10:45**MOT test number** 527402852034**Result** ✗ Failed

- Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #6 2015-02-12 16:03**MOT test number** 165223845459**Result** ✓ Passed

**MOT #5** 2015-02-12 10:00**MOT test number** 935263945086**Result** ✗ Failed

- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)

MOT #4 2013-08-17 12:40**MOT test number** 809629923208**Result** ✓ Passed

- Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)

MOT #3 2012-09-01 12:04**MOT test number** 305435042280**Result** ✓ Passed**MOT #2** 2011-08-16 14:21**MOT test number** 518158721264**Result** ✓ Passed**MOT #1** 2010-09-01 10:59**MOT test number** 793784040299**Result** ✓ Passed

- Notice** Full inspection of vehicle prevented by fitting of sill trims
- Advice** Offside Inner Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Inner Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
7 December 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	7 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2007-09-13
Last registration	2023-12-08
Complete history	See info



Registration #1	2007-09-13	28 mi
Registration #2	2010-09-01	46.392 mi
Registration #3	2011-08-16	54.307 mi
Registration #4	2012-09-01	61.989 mi
Registration #5	2013-08-17	68.489 mi
Registration #6	2015-02-12	80.734 mi
Registration #7	2015-02-12	80.734 mi
Registration #8	2016-02-23	92.389 mi
Registration #9	2016-02-23	92.389 mi
Registration #10	2017-02-01	105.705 mi
Registration #11	2017-02-01	105.705 mi
Registration #12	2017-10-16	115.219 mi
Registration #13	2017-10-18	115.220 mi
Registration #14	2019-05-20	121.217 mi
Registration #15	2019-05-20	121.217 mi
Registration #16	2019-05-20	121.217 mi
Registration #17	2019-05-20	121.217 mi
Registration #18	2019-05-20	121.217 mi
Registration #19	2019-05-20	121.217 mi
Registration #20	2019-05-20	121.217 mi
Registration #21	2019-05-20	121.217 mi
Registration #22	2019-05-20	121.217 mi
Registration #23	2019-05-20	121.217 mi
Registration #24	2019-05-20	121.217 mi
Registration #25	2019-05-20	121.217 mi
Registration #26	2019-05-20	121.217 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1784 mm
Length	4798 mm
Wheel base	2857 mm
Kerb weight	2147 kg
Max. allowed weight	2760 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Engine number	180806B12131
---------------	--------------