



**GXI2FVW**

report date: 2024-03-29

General information

Make	FORD
Model	MONDEO EDGE TDCI
Colour	White
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg





Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://autoonline.co.uk)



MOT history

MOT #11 2023-10-30 14:06

MOT test number 515105051393

Result ✓ Passed

Next expiry date 2024-10-29

- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Instrument panel indicating engine malfunction, also sticker on clocks will require further investigation.
- Advice** Oil resting on top of engine
- Advice** Rear Tyre worn close to legal limit/worn on edge Both on inner edge (5.2.3 (e))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Slight fuming coming from engine

**MOT #10**

2023-10-27 14:05

**MOT test number**

486491897901

**Result****✗ Failed**

- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Slight fuming coming from engine
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Tyre worn close to legal limit/worn on edge Both on inner edge (5.2.3 (e))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Instrument panel indicating engine malfunction, also sticker on clocks will require further investigation.
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Oil resting on top of engine
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #9**

2022-10-22 13:49

**MOT test number**

363343721477

**Result****✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear trailing arm bushes slightly Debonded
- Advice** Nearside Front Tyre worn on edges



MOT #8	2022-10-22 13:49
MOT test number	534217241760
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))
Advice	Rear trailing arm bushes slightly Debonded
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Tyre worn on edges

MOT #7	2021-10-26 08:25
MOT test number	299775356315
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear trailing arm bushes slightly perished

**MOT #6** 2021-10-20 15:13**MOT test number** 423819975888**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear trailing arm bushes slightly perished**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Front Brakes imbalanced across an axle by more than 50% (1.2.1 (b) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #5** 2020-09-08 14:28**MOT test number** 148411721151**Result** ✓ Passed**MOT #4** 2019-11-09 09:38**MOT test number** 849866219078**Result** ✓ Passed**MOT #3** 2018-12-03 14:33**MOT test number** 306758774382**Result** ✓ Passed



MOT #2	2018-12-03 14:12
MOT test number	152125165569
Result	✗ Failed
<div>Fail</div> Offside Front Position lamp not working (4.2.1 (a))	

MOT #1	2018-03-07 07:36
MOT test number	838195127653
Result	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2019-06-29
Current registration	 XXXXX
Plate since	2019-06-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2012-06-01
Last registration	2023-10-30
Complete history	<a href="#">See info</a>



Registration #1	2012-06-01	26 mi
Registration #2	2018-03-07	115.220 mi
Registration #3	2018-12-03	115.386 mi
Registration #4	2018-12-03	115.386 mi
Registration #5	2019-10-20	115.386 mi
Registration #6	2021-10-20	133.912 mi
Registration #7	2023-10-30	133.912 mi
Registration #8	2023-10-30	133.912 mi
Registration #9	2023-10-30	133.912 mi
Registration #10	2023-10-30	133.912 mi
Registration #11	2023-10-30	133.912 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1886 mm
Height	1512 mm
Length	4830 mm
Wheel base	2850 mm
Kerb weight	1557 kg
Max. allowed weight	2290 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number CR58887