




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	Beige
Year of manufacture	2011
Top speed	111 mph
0 - 100 km/h	11.6 seconds
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 kW / 102 HP / 102 BHP
Max. torque	148 Nm at 3.800 rpm
Engine capacity	1.595 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	37.7 mpg
CO2 emission	180 g/km
CO2 label	I






Internet history

Entry 1

Date	2022-02-07
Pictures	9
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-11
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	12
Total items failed	7

MOT #152024-02-12 13:05

MOT test number576228654995

Result✓ Passed

Next expiry date2025-02-11

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

MOT #142023-02-10 10:22

MOT test number508328014164

Result✓ Passed

Minor Offside Front Tyre obviously under inflated (5.2.3 (l))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #132022-02-12 12:11

MOT test number804637387910

Result✓ Passed

Advice Rear axle covered with under body seal**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12** 2021-07-15 14:30**MOT test number** 227854624011**Result** ✓ Passed**Advice** Nearside Front Position lamp slightly affected by the operation of another lamp (4.2.3 (c))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #11** 2020-07-13 08:40**MOT test number** 967106178166**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #10** 2020-07-09 13:35**MOT test number** 990425449154**Result** ✗ Failed**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Fail** Reversing lamp inoperative (4.6.1 (a))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Rear Brake disc worn, but not excessively Appear to have overheated, discoloured (1.1.14 (a) (i))**MOT #9** 2019-07-27 09:56**MOT test number** 892026895957**Result** ✓ Passed

**MOT #8** 2019-07-13 10:44**MOT test number** 684803322439**Result** ✗ Failed**Fail** Emissions oxygen sensor obviously defective (8.2.2.1 (a))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #7** 2018-07-05 12:13**MOT test number** 489117523077**Result** ✓ Passed**MOT #6** 2017-07-06 14:21**MOT test number** 747271719973**Result** ✓ Passed**MOT #5** 2017-07-06 12:24**MOT test number** 478666524688**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2016-07-11 14:10**MOT test number** 548984738637**Result** ✓ Passed**MOT #3** 2016-07-11 13:30**MOT test number** 231720866511**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #2	2015-07-02 11:50
MOT test number	296273185124
Result	✓ Passed
MOT #1	2014-07-03 12:02
MOT test number	266504584110
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
11 February 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	11 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-01-13
Last registration	2024-02-12
Complete history	See info



Registration #1	2011-01-13	11 mi
Registration #2	2014-07-03	34.547 mi
Registration #3	2015-07-02	40.875 mi
Registration #4	2016-07-11	46.178 mi
Registration #5	2016-07-11	46.178 mi
Registration #6	2017-07-06	62.253 mi
Registration #7	2017-07-06	62.253 mi
Registration #8	2018-07-05	76.545 mi
Registration #9	2019-07-13	84.909 mi
Registration #10	2020-07-06	93.277 mi
Registration #11	2021-07-06	93.277 mi
Registration #12	2022-07-06	93.277 mi
Registration #13	2023-07-06	93.277 mi
Registration #14	2024-02-12	93.277 mi
Registration #15	2024-02-12	93.277 mi
Registration #16	2024-02-12	93.277 mi
Registration #17	2024-02-12	93.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1721 mm
Height	1502 mm
Length	4129 mm
Wheel base	2516 mm
Kerb weight	1177 kg
Max. allowed weight	1680 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BFS 085648