



SL59NTN

report date: 2024-03-29

General information

Make	FIAT
Model	GRANDE PUNTO ACTIVE
Colour	Grey
Year of manufacture	-
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-08-01
Pictures	9
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-30
Pictures	6
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT #12	2021-02-17 10:19
MOT test number	852791368797
Result	✓ Passed
Next expiry date	2022-02-16
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Coil spring corroded all 4 (5.3.1 (b) (i))
Advice	Rear Exhaust mounting defective (6.1.2 (a))

MOT #11	2020-01-27 11:52
MOT test number	655634085398
Result	✓ Passed
Advice	Coil spring corroded all 4 (5.3.1 (b) (i))
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Nearside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #10	2019-01-14 11:55
MOT test number	650302880334
Result	✓ Passed
Advice	Coil spring corroded both front (5.3.1 (b) (i))

MOT #9	2017-12-20 15:39
MOT test number	580172770689
Result	✓ Passed
Advice	Nearside Front Inner Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)
Advice	Parking brake lever has little reserve travel (3.1.6b)
Advice	Nearside Front Inner Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8**

2017-01-18 13:21

MOT test number

661705769351

Result

✓ Passed

Advice Supplementary Restraint System warning lamp does not illuminate (5.4.2)**Advice** Front Tyre worn close to the legal limit o/s/n/s (4.1.E.1)**MOT #7**

2017-01-16 16:53

MOT test number

318660634056

Result

✗ Failed

Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Fail** Battery insecure (1.9.1)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Advice** Front Tyre worn close to the legal limit o/s/n/s (4.1.E.1)**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Fail** Nearside Headlamp aim too low (1.8)**Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Front Ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt o/s/n/s (2.2.C.1c)**Fail** Front position lamp(s) not working o/n/s (1.1.A.3b)**Advice** Supplementary Restraint System warning lamp does not illuminate (5.4.2)**Fail** Nearside Headlamp insecure (1.7.3)

**MOT #6** 2016-01-18 16:07**MOT test number** 246192800118**Result** ✓ Passed

- Advice** N/s/f wheel arch missing
- Advice** Supplementary Restraint System warning lamp does not illuminate (5.4.2)
- Advice** Both front tyres has small tears on outer wall
- Advice** Nearside Front Vehicle structure has slight damage (6.1.A.1)

MOT #5 2016-01-18 11:57**MOT test number** 206699377768**Result** ✗ Failed

- Fail** Front Exhaust has a major leak of exhaust gases flexi (7.1.2)
- Fail** Driver's seat fore and aft adjustment mechanism not functioning as intended. (6.2.A.3)
- Fail** Offside Front position lamp(s) insecure (1.1.A.3a)
- Advice** Both front tyres has small tears on outer wall
- Advice** Nearside Front Vehicle structure has slight damage (6.1.A.1)
- Fail** Rear Exhaust has a major leak of exhaust gases backbox (7.1.2)
- Fail** Nearside Front position lamp(s) insecure (1.1.A.3a)
- Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)
- Advice** N/s/f wheel arch missing

**MOT #4**

2015-01-15 12:42

MOT test number

625375415077

Result

✓ Passed

- Notice** Exhaust system corroded but not excessive
- Advice** Shock absorber has slight corrosion to the casing (2.7.2a)
- Notice** N/s/f chassis has rubber sealant
- Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** O/s/f anti roll bar gators covered in tape
- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Front Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)
- Notice** Front mac rough
- Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Notice** Oil leak
- Advice** Parking brake lever has little reserve travel (3.1.6b)

MOT #3

2013-09-10 16:55

MOT test number

749583453260

Result

✓ Passed

- Advice** Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)



MOT #2	2013-09-10 16:55
MOT test number	527603153215
Result	✗ Failed
Advice	Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)
Pass with rectification	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1	2012-08-25 16:55
MOT test number	326038732288
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-09-29
Last registration	2021-02-17
Complete history	See info



Registration #1	2009-09-29	10 mi
Registration #2	2012-08-25	10.503 mi
Registration #3	2013-09-10	17.946 mi
Registration #4	2015-01-15	30.129 mi
Registration #5	2016-01-18	44.068 mi
Registration #6	2016-01-18	44.013 mi
Registration #7	2017-01-16	46.962 mi
Registration #8	2018-01-16	50.000 mi
Registration #9	2018-01-16	50.000 mi
Registration #10	2018-01-16	50.000 mi
Registration #11	2018-01-16	50.000 mi
Registration #12	2018-01-16	50.000 mi
Registration #13	2018-01-16	50.000 mi
Registration #14	2018-01-16	50.000 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9519694