



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	MATRIX GSI
Colour	Blue
Year of manufacture	-
Top speed	103 mph
0 - 60 mph	14.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	101 BHP
Max. torque	141 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	21.9 mpg
Consumption extra urban	31.0 mpg
Consumption combined	26.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-05-22
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

**MOT history**

<b>MOT #23</b>	2023-09-28 14:28
<b>MOT test number</b>	528332432156
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-09-30
<b>Advice</b>	Both front tyres worn on inner edge

<b>MOT #22</b>	2023-09-28 10:06
<b>MOT test number</b>	108853040458
<b>Result</b>	✗ Failed
<b>Fail</b>	Brake performance unable to be tested (1.2.1 (g))
<b>Advice</b>	Both front tyres worn on inner edge
<b>Fail</b>	Offside Front Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))

<b>MOT #21</b>	2022-09-28 09:06
<b>MOT test number</b>	789689332317
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive outer sill (5.3.6 (a) (i))
<b>Advice</b>	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Advice</b>	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

<b>MOT #20</b>	2021-10-01 09:31
<b>MOT test number</b>	557327980691
<b>Result</b>	✓ Passed
<b>Minor</b>	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #19**

2020-09-16 13:07

**MOT test number**

640435532682

**Result**

✓ Passed

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #18**

2020-09-16 13:07

**MOT test number**

332333505876

**Result**

✗ Failed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Pass with rectification** Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #17**

2019-09-18 13:16

**MOT test number**

303036574320

**Result**

✓ Passed

**MOT #16**

2018-09-18 12:05

**MOT test number**

882189777430

**Result**

✓ Passed

**MOT #15** 2017-09-20 13:12**MOT test number** 694110561975**Result** ✓ Passed**MOT #14** 2017-09-14 11:44**MOT test number** 838108928384**Result** ✗ Failed**Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)**Fail** Nearside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)**MOT #13** 2016-09-14 10:35**MOT test number** 587697387697**Result** ✓ Passed**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #12** 2015-09-14 11:57**MOT test number** 437006198682**Result** ✓ Passed**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #11** 2014-09-09 15:27**MOT test number** 879062754240**Result** ✓ Passed**MOT #10** 2013-09-13 11:15**MOT test number** 535116053281**Result** ✓ Passed

**MOT #9** 2012-09-13 12:59**MOT test number** 378027652426**Result** ✓ Passed**MOT #8** 2011-09-10 12:55**MOT test number** 109063351208**Result** ✓ Passed**Notice** Nail in offside rear tyre**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2011-09-08 16:04**MOT test number** 929511651209**Result** ✗ Failed**Fail** Offside Front Brake hose leaking (3.6.A.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Power steering pipe(s) or hose(s) leaking from a seal (2.3.3b)**Notice** Nail in offside rear tyre**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #6** 2010-09-13 10:35**MOT test number** 512466450254**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2010-09-13 10:26**MOT test number** 420626350266**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Headlamp aim too high (1.8)**Fail** Nearside Headlamp aim too high (1.8)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2009-09-17 17:22**MOT test number** 354510469485**Result** ✓ Passed**MOT #3** 2009-02-27 14:07**MOT test number** 641258959012**Result** ✓ Passed**MOT #2** 2008-03-03 16:52**MOT test number** 451503368009**Result** ✓ Passed**MOT #1** 2007-03-13 12:32**MOT test number** 964142977023**Result** ✓ Passed



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-03-18
Last registration	2023-09-28
Complete history	<a href="#">See info</a>



Registration #1	2004-03-18	19 mi
Registration #2	2007-03-13	13.340 mi
Registration #3	2008-03-03	23.347 mi
Registration #4	2009-02-27	30.919 mi
Registration #5	2009-09-17	35.933 mi
Registration #6	2010-09-13	41.477 mi
Registration #7	2010-09-13	41.477 mi
Registration #8	2011-09-08	46.469 mi
Registration #9	2011-09-10	46.469 mi
Registration #10	2012-09-13	52.330 mi
Registration #11	2013-09-13	57.841 mi
Registration #12	2014-09-09	63.101 mi
Registration #13	2015-09-14	68.288 mi
Registration #14	2016-09-14	73.475 mi
Registration #15	2017-09-14	78.662 mi
Registration #16	2018-09-14	83.849 mi
Registration #17	2019-09-14	89.036 mi
Registration #18	2020-09-14	94.223 mi
Registration #19	2021-09-14	99.410 mi
Registration #20	2022-09-14	104.597 mi
Registration #21	2023-09-14	109.784 mi
Registration #22	2024-03-28	114.971 mi
Registration #23	2024-03-28	114.971 mi
Registration #24	2024-03-28	114.971 mi
Registration #25	2024-03-28	114.971 mi



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1740 mm
Height	1635 mm
Length	4025 mm
Wheel base	2600 mm
Kerb weight	1349 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	G4ED3708526