



PEUGEOT




report date: 2024-03-28

General information

Make	PEUGEOT
Model	407 THP CC SE
Colour	Red
Year of manufacture	2009
Top speed	134 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	240 Nm at 1.400 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.4 mpg
Consumption extra urban	50.4 mpg
Consumption combined	37.7 mpg
CO2 emission	155 g/km
CO2 label	G





Internet history

Entry 1	
Date	2021-12-09
Pictures	12
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-10-06
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	50
Total items failed	20

MOT #18 2023-10-07 13:50

MOT test number 930536896487

Result ✓ Passed

Next expiry date 2024-10-06

- Advice** Front Suspension arm corroded but not seriously weakened both sides (5.3.3 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #17 2023-09-06 16:31

MOT test number 583834756241

Result ✗ Failed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, but not excessively offside and nearside (1.1.14 (a) (i))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Pass with rectification** Front Windscreen washer not working (3.5 (a))
- Advice** Front Suspension arm corroded but not seriously weakened offside and nearside (5.3.3 (b) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #16**

2022-01-29 10:05

**MOT test number**

939906433512

**Result****✗ Failed**

- Advice** Rear Brake disc worn, but not excessively offside and nearside (1.1.14 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #15**

2021-01-09 12:34

**MOT test number**

521963091189

**Result****✓ Passed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
- Advice** Offside Rear Nail in tyre
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
- Advice** Play in steering rack inner joint(s)
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #14**

2021-01-08 14:13

**MOT test number**

135859683842

**Result****✗ Failed****Fail**

Nearside Front Lower Suspension arm attachment bracket/mounting insecure and impairing directional stability marked yellow (5.3.3 (a) (ii))

**Fail**

Nearside Front Tyre not fitted in accordance with side wall instructions inside/out (5.2.3 (i))

**Fail**

Offside Rear Direction indicator incorrect colour (4.4.3 (a))

**Advice**

Offside Rear Nail in tyre

**Minor**

Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice**

Offside Rear Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

**Advice**

Offside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice**

Offside Rear Service brake binding but not excessively (1.2.1 (f))

**Fail**

Offside Side repeater incorrect colour lens missing (4.4.3 (a))

**Advice**

Play in steering rack inner joint(s)

**Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

**Fail**

Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

**Advice**

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Fail**

Offside Front Service brake excessively binding (1.2.1 (f))

**Fail**

Nearside Front Lower Suspension arm pin or bush excessively worn marked yellow (5.3.4 (a) (i))

**Fail**

Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #13**

2020-01-24 11:01

**MOT test number**

524386340977

**Result**

✓ Passed

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Minor** Nearside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (ii))
- Advice** Exhaust rear heat shield insecure
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

**MOT #12**

2019-01-18 15:08

**MOT test number**

799332176678

**Result**

✓ Passed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Inner Brake pad(s) wearing thin borderline pass (1.1.13 (a) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Lower Suspension component pin or bush slightly worn lower suspension joint(crows foot) borderline pass (5.3.4 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Inner Steering linkage ball joint has slight play slight play in inner track control arm (2.1.3 (b) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2018-02-16 12:00**MOT test number** 975308391933**Result** ✓ Passed**MOT #10** 2018-02-16 12:00**MOT test number** 649802199781**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**MOT #9** 2017-02-10 15:45**MOT test number** 878152333404**Result** ✓ Passed**MOT #8** 2017-02-10 15:45**MOT test number** 306077476431**Result** ✗ Failed**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**MOT #7** 2016-01-21 09:19**MOT test number** 924525010213**Result** ✓ Passed**Advice** Front under tray insecure**MOT #6** 2015-01-20 09:00**MOT test number** 439360125029**Result** ✓ Passed

**MOT #5** 2014-03-10 15:33**MOT test number** 537689564045**Result** ✓ Passed**MOT #4** 2014-03-10 10:41**MOT test number** 256349864018**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #3** 2013-03-11 15:37**MOT test number** 507440073051**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-03-11 15:01**MOT test number** 227160773047**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #1** 2012-03-16 09:47**MOT test number** 378616872042**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
6 October 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	279
<b>MOT expiry date</b>	6 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>NU09GHK</b>
Plate since	2019-03-28
Current registration	<b>NU09GHK</b>
Plate since	2019-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-03-19
Last registration	2023-10-07
Complete history	<a href="#">See info</a>



Registration #1	2009-03-19	24 mi
Registration #2	2012-03-16	35.243 mi
Registration #3	2013-03-11	46.213 mi
Registration #4	2013-03-11	46.213 mi
Registration #5	2014-03-10	55.333 mi
Registration #6	2014-03-10	55.333 mi
Registration #7	2015-01-20	62.050 mi
Registration #8	2016-01-21	66.342 mi
Registration #9	2017-02-10	69.819 mi
Registration #10	2017-02-10	69.819 mi
Registration #11	2018-03-20	75.333 mi
Registration #12	2018-03-20	75.333 mi
Registration #13	2019-03-20	80.333 mi
Registration #14	2019-03-20	80.333 mi
Registration #15	2020-03-20	85.333 mi
Registration #16	2020-03-20	85.333 mi
Registration #17	2021-03-20	90.333 mi
Registration #18	2021-03-20	90.333 mi
Registration #19	2022-03-20	95.333 mi
Registration #20	2023-10-07	100.333 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1817 mm
Height	1426 mm
Length	4400 mm
Wheel base	2605 mm
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2

**Engine number**

DYXH4000054