



PEUGEOT




report date: 2024-03-29

General information

Make	PEUGEOT
Model	307 ALLURE COUPE CABRIOLET
Colour	Blue
Year of manufacture	2007
Top speed	119 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	45.6 mpg
Consumption combined	37.2 mpg
CO2 emission	178 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-07-14
Pictures	15
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-02
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	27
Total items failed	8

MOT #17	2023-05-03 10:17
MOT test number	526132622944
Result	✓ Passed
Next expiry date	2024-05-02
Advice	Items removed from driver's view prior to test
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Passenger seat(s) missing at time of test

MOT #16	2023-05-03 10:17
MOT test number	981635402930
Result	✗ Failed
Pass with rectification	Offside Rear Position lamp not working (4.2.1 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Items removed from driver's view prior to test
Pass with rectification	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Rear Passenger seat(s) missing at time of test
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #15** 2022-03-09 14:26**MOT test number** 175437979457**Result** ✓ Passed**Minor** Nearside Rear Lower Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Minor** Registration plate lamp missing in the case of multiple lamps or light sources lenz only (4.7.1 (b) (i))**Minor** Offside Rear Upper Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**MOT #14** 2020-09-22 08:38**MOT test number** 634170767836**Result** ✓ Passed**MOT #13** 2019-08-13 23:06**MOT test number** 804075901473**Result** ✓ Passed**Advice** Central Lower Engine mounting damaged but not to excess (6.1.8 (a) (i))**Advice** Offside Front Suspension component ball joint has slight play (5.3.4 (a) (i))**MOT #12** 2019-08-13 23:06**MOT test number** 235252678347**Result** ✗ Failed**Advice** Offside Front Suspension component ball joint has slight play (5.3.4 (a) (i))**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Central Lower Engine mounting damaged but not to excess (6.1.8 (a) (i))**MOT #11** 2018-09-07 14:40**MOT test number** 455456555352**Result** ✓ Passed

**MOT #10** 2018-09-07 14:40**MOT test number** 338811610845**Result** ✗ Failed**Pass with rectification** Rear Stop lamp(s) all not working (4.3.1 (a) (iii))**Pass with rectification** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #9** 2017-09-06 12:14**MOT test number** 862486285454**Result** ✓ Passed**MOT #8** 2016-09-08 14:56**MOT test number** 933251360011**Result** ✓ Passed**Advice** Offside Rear tyre cut in outer side wall**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2016-09-08 13:17**MOT test number** 230447768876**Result** ✗ Failed**Fail** Offside Lower Front suspension ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Nearside Side repeater insecure (1.4.A.2b)**Advice** Offside Rear tyre cut in outer side wall**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Body has a sharp edge caused by damage wing (6.1.C.1)**MOT #6** 2015-09-04 16:38**MOT test number** 681438251200**Result** ✓ Passed

**MOT #5** 2014-08-27 15:42**MOT test number** 608929034250**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-09-02 10:52**MOT test number** 857195943225**Result** ✓ Passed**MOT #3** 2012-08-31 13:42**MOT test number** 356054242287**Result** ✓ Passed**Notice** Passenger seat(s) missing at time of test**Notice** FOG LIGHT NOT WORKING ON TRAILER SOCKET**MOT #2** 2011-09-02 10:11**MOT test number** 745795141201**Result** ✓ Passed**Notice** FRONT DISCS BADLY WORN & LIPPED (PLZ REF2SPEC).**Notice** O/S REAR TYRE ON MARKER .Thanx..**MOT #1** 2010-09-04 09:02**MOT test number** 930497940287**Result** ✓ Passed**Notice** Nail in nearside rear tyre



Tax & MOT check

X

Untaxed

Tax expired:  
31 October 2023

✓

MOT

Expires:  
2 May 2024

Tax status	Expired at 31 October 2023
Days left	182 days too late
MOT expiry date	2 May 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>KF07BNH</b>
Plate since	2019-03-29
Current registration	<b>KF07BNH</b>
Plate since	2019-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-08-30
Last registration	2023-05-03
Complete history	<a href="#">See info</a>



Registration #1	2007-08-30	15 mi
Registration #2	2010-09-04	15.393 mi
Registration #3	2011-09-02	22.549 mi
Registration #4	2012-08-31	27.764 mi
Registration #5	2013-09-02	35.264 mi
Registration #6	2014-08-27	43.821 mi
Registration #7	2015-09-04	53.444 mi
Registration #8	2016-09-08	60.384 mi
Registration #9	2016-09-08	60.384 mi
Registration #10	2017-09-06	67.649 mi
Registration #11	2018-09-06	75.000 mi
Registration #12	2019-09-06	82.351 mi
Registration #13	2020-09-06	89.702 mi
Registration #14	2021-09-06	97.053 mi
Registration #15	2022-09-06	104.404 mi
Registration #16	2023-05-03	111.755 mi
Registration #17	2023-05-03	111.755 mi
Registration #18	2023-05-03	111.755 mi
Registration #19	2023-05-03	111.755 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1757 mm
Height	1440 mm
Length	4357 mm
Wheel base	2605 mm
Kerb weight	1528 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	FX7U3288774