



report date: 2024-03-28

General information

Make	FORD
Model	FIESTA ZETEC S
Colour	Blue
Year of manufacture	2010
Top speed	120 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	152 Nm at 4.050 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.9 mpg
CO2 emission	134 g/km
CO2 label	E





MOT history

MOT expiry date	2024-05-31
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	23
Total items failed	6

MOT #13	2023-05-31 15:34
MOT test number	797671186749
Result	✓ Passed
Next expiry date	2024-05-31
Advice	Brake pad(s) wearing thin both front (1.1.13 (a) (ii))

MOT #12	2023-05-31 14:41
MOT test number	709204330505
Result	✗ Failed
Advice	Brake pad(s) wearing thin both front (1.1.13 (a) (ii))
Fail	Offside Rear Road wheel fixing missing (5.2.1 (a) (i))

MOT #11	2022-06-01 16:05
MOT test number	989431698461
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #10**

2020-08-04 15:10

MOT test number

273775955194

Result

✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front tyre has slight damage on outer wall
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9

2020-08-04 14:33

MOT test number

280672382664

Result

✗ Failed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Direction indicator not working (4.4.1 (a) (ii))
- Advice** Nearside Front tyre has slight damage on outer wall

MOT #8

2018-05-29 10:21

MOT test number

189116158592

Result

✓ Passed

- Advice** Rear exhaust heatsheild insucure.
- Advice** Travel on service brake pedal.

**MOT #7** 2017-05-23 11:22**MOT test number** 955630989884**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit worn on inner edge (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit worn on inner edge (4.1.E.1)**MOT #6** 2016-05-16 10:12**MOT test number** 548585269677**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-05-16 10:12**MOT test number** 793178355644**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #4** 2015-05-11 08:58**MOT test number** 739311735157**Result** ✓ Passed**MOT #3** 2014-05-19 09:12**MOT test number** 475079734129**Result** ✓ Passed



MOT #2	2013-05-29 14:29
MOT test number	236629443135
Result	✓ Passed
Notice	Vehicle's internal headlight adjuster altered to recheck lights

MOT #1	2013-05-28 14:30
MOT test number	479428843195
Result	✗ Failed
Fail	Nearside Front Road wheel bead rim badly distorted (4.2.A.1a)
Pass with rectification	Nearside Headlamp aim too low (1.8)
Notice	Vehicle's internal headlight adjuster altered to recheck lights



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
31 May 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	31 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	KT10VVM
Plate since	2019-03-28
Current registration	KT10VVM
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-05-29
Last registration	2023-05-31
Complete history	See info



Registration #1	2010-05-29	23 mi
Registration #2	2013-05-28	14.409 mi
Registration #3	2013-05-29	14.409 mi
Registration #4	2014-05-19	22.485 mi
Registration #5	2015-05-11	30.520 mi
Registration #6	2016-05-16	31.971 mi
Registration #7	2016-05-16	31.971 mi
Registration #8	2016-05-16	31.971 mi
Registration #9	2016-05-16	31.971 mi
Registration #10	2016-05-16	31.971 mi
Registration #11	2016-05-16	31.971 mi
Registration #12	2016-05-16	31.971 mi
Registration #13	2016-05-16	31.971 mi
Registration #14	2016-05-16	31.971 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1973 mm
Height	1481 mm
Length	3953 mm
Kerb weight	1045 kg
Max. allowed weight	1500 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2

