



report date: 2024-03-28

General information

Make	CITROEN
Model	C2 16V VTS
Colour	Red
Year of manufacture	-
Top speed	126 mph
0 - 60 mph	8.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	142 Nm at 3.750 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg



LABEL UNKNOWN

**MOT history**

<b>MOT #16</b>	2020-07-03 10:46
<b>MOT test number</b>	898346592859
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-07-27
<b>Advice</b>	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
<b>Advice</b>	Offside Front Direction indicator slightly discoloured (4.4.3 (a))
<b>Advice</b>	Nearside Front Front fog lamp inop

<b>MOT #15</b>	2020-06-30 08:37
<b>MOT test number</b>	729673505130
<b>Result</b>	✗ Failed
<b>Advice</b>	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
<b>Advice</b>	Nearside Front Front fog lamp inop
<b>Advice</b>	Offside Front Direction indicator slightly discoloured (4.4.3 (a))
<b>Fail</b>	Rear Outer Suspension component mounting prescribed area is corroded to the extent that control of the vehicle is likely to be adversely affected Both NSR & OSR outer sills (5.3.6 (a) (ii))
<b>Fail</b>	Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
<b>Fail</b>	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
<b>Fail</b>	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

<b>MOT #14</b>	2019-07-22 10:55
<b>MOT test number</b>	240186503982
<b>Result</b>	✓ Passed

**MOT #13**

2019-07-22 09:09

**MOT test number**

151958939855

**Result**

✗ Failed

**Fail** Nearside Rear Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Fail** Offside Front Inner Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #12**

2018-07-25 09:27

**MOT test number**

431299521583

**Result**

✓ Passed

**Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**Advice** Nearside Rear bump stop missing

**Advice** Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced at bump stop (6.1.1 (c) (i))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced at bump stop (6.1.1 (c) (i))

**MOT #11**

2017-07-06 13:06

**MOT test number**

439730217044

**Result**

✓ Passed

**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Under body corrosion

**Advice** Offside Front Ball joint has slight play (2.2.B.1f)

**MOT #10** 2016-07-20 09:20**MOT test number** 782291786149**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2015-07-04 09:53**MOT test number** 927035985167**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2015-07-04 09:53**MOT test number** 155535785114**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2014-07-26 13:42**MOT test number** 935717104214**Result** ✓ Passed**Advice** Offside Brake cable has wires broken but is not significantly weakened (3.5.1b)**Notice** Rear exhaust hanger is broken**Notice** Nearside front tyre has a damaged sidewall

**MOT #6**

2014-07-26 09:46

**MOT test number**

217667804221

**Result****✗ Failed****Advice** Offside Brake cable has wires broken but is not significantly weakened (3.5.1b)**Notice** Rear exhaust hanger is broken**Fail** Offside Front coil spring broken (2.4.C.1a)**Notice** Nearside front tyre has a damaged sidewall**MOT #5**

2013-07-25 09:31

**MOT test number**

426926303261

**Result****✓ Passed****Advice** Offside Rear Brake cable has wires broken but is not significantly weakened (3.5.1b)**Notice** Nearside front tyre sidewall is damaged**Notice** Rear tyres are cracked and split in the treads**Notice** Rear tyres are very low**MOT #4**

2012-07-28 09:55

**MOT test number**

719180612290

**Result****✓ Passed****Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in offside rear tyre**Advice** Offside Rear Brake cable has wires broken but is not significantly weakened (3.5.1b)**Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Notice** Offside rear brake slightly binding (possibly sticking brake pads)



MOT #3	2011-07-13 10:06
MOT test number	515814891107
Result	✓ Passed
MOT #2	2010-06-03 10:50
MOT test number	382994550111
Result	✓ Passed
MOT #1	2009-02-18 08:19
MOT test number	421519349091
Result	✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2005-11-21
Last registration	2020-07-03
Complete history	<a href="#">See info</a>



Registration #1	2005-11-21	21 mi
Registration #2	2009-02-18	21.518 mi
Registration #3	2010-06-03	31.370 mi
Registration #4	2011-07-13	43.101 mi
Registration #5	2012-07-28	51.251 mi
Registration #6	2013-07-25	56.678 mi
Registration #7	2014-07-26	62.493 mi
Registration #8	2014-07-26	62.493 mi
Registration #9	2015-05-20	65.277 mi
Registration #10	2015-05-20	65.277 mi
Registration #11	2015-05-20	65.277 mi
Registration #12	2015-05-20	65.277 mi
Registration #13	2015-05-20	65.277 mi
Registration #14	2015-05-20	65.277 mi
Registration #15	2015-05-20	65.277 mi
Registration #16	2015-05-20	65.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1659 mm
Height	1451 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	1083 kg
Max. allowed weight	1394 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Engine number	FX4S2476190