




report date: 2024-03-29

General information

Make	FORD
Model	C-MAX ZETEC 100
Colour	Blue
Year of manufacture	2009
Top speed	107 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	146 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	164 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-02-23
Pictures	28
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-03-29
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	29
Total items failed	0

MOT #17	2024-03-30 15:13
MOT test number	447794229259
Result	✓ Passed
Next expiry date	2025-03-29
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement NS&OS (5.3.4 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #16	2024-03-30 14:31
MOT test number	735170076950
Result	✗ Failed
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement NS&OS (5.3.4 (a) (i))
DANGEROUS	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #15**

2023-03-27 15:46

MOT test number

335039010408

Result

✓ Passed

- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear (5.3.4 (a) (i))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear (5.3.4 (a) (i))

MOT #14

2022-03-10 17:11

MOT test number

649806636129

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #13

2022-03-04 16:59

MOT test number

318140671355

Result

✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #12** 2021-03-04 16:02**MOT test number** 930092657494**Result** ✓ Passed**MOT #11** 2020-03-21 08:37**MOT test number** 636341121588**Result** ✓ Passed**Advice** Nearside Front Inner Play in steering rack inner joint(s)**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (Deteriorated) (5.3.4 (a) (i))**MOT #10** 2020-03-10 14:25**MOT test number** 889549756465**Result** ✗ Failed**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (Deteriorated) (5.3.4 (a) (i))**MAJOR** Offside Front Windscreen washer not working (3.5 (a))**Advice** Nearside Front Inner Play in steering rack inner joint(s)**MAJOR** Nearside Front Windscreen washer not working (3.5 (a))**MOT #9** 2019-03-14 14:05**MOT test number** 288781616351**Result** ✓ Passed**MOT #8** 2019-03-14 09:54**MOT test number** 225769822342**Result** ✗ Failed**MAJOR** Windscreen washer not working (3.5 (a))

**MOT #7** 2018-03-19 13:01**MOT test number** 264380282306**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2017-03-08 13:59**MOT test number** 273873637398**Result** ✓ Passed**MOT #5** 2016-03-15 10:50**MOT test number** 652594008599**Result** ✓ Passed**MOT #4** 2015-03-17 12:59**MOT test number** 795696575023**Result** ✓ Passed**MOT #3** 2014-03-17 09:38**MOT test number** 359256074063**Result** ✓ Passed**MOT #2** 2013-03-12 09:44**MOT test number** 705801873098**Result** ✓ Passed**MOT #1** 2012-03-13 10:17**MOT test number** 175343972487**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
29 March 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	29 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	LD09CUC
Plate since	2019-03-29
Current registration	LD09CUC
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-03-24
Last registration	2024-03-30
Complete history	See info



Registration #1	2009-03-24	21 mi
Registration #2	2012-03-13	22.425 mi
Registration #3	2013-03-12	30.994 mi
Registration #4	2014-03-17	39.499 mi
Registration #5	2015-03-17	47.099 mi
Registration #6	2016-03-15	55.854 mi
Registration #7	2017-03-08	68.423 mi
Registration #8	2018-03-19	76.167 mi
Registration #9	2019-03-14	81.964 mi
Registration #10	2019-03-14	81.964 mi
Registration #11	2020-03-20	81.964 mi
Registration #12	2021-03-20	81.964 mi
Registration #13	2022-03-20	81.964 mi
Registration #14	2023-03-20	81.964 mi
Registration #15	2024-03-20	81.964 mi
Registration #16	2025-03-20	81.964 mi
Registration #17	2026-03-20	81.964 mi
Registration #18	2027-03-20	81.964 mi
Registration #19	2028-03-20	81.964 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1372 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	8L07676