





General information

| Make | VAUXHALL |
|---------------------|-------------------|
| Model | ASTRA SRI S/S |
| Colour | Blue |
| Year of manufacture | 2018 |
| Top speed | 130 mph |
| 0 - 60 mph | 8.4 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 148 BHP |
|-------------------------|---------------------|
| Max. torque | 235 Nm at 2.000 rpm |
| Engine capacity | 1.399 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 39.2 mpg |
| Consumption extra urban | 62.8 mpg |
| Consumption combined | 51.4 mpg |
| CO2 emission | 127 g/km |
| CO2 label | D |





| Internet history | |
|------------------|-------------|
| Entry 1 | |
| Date | 2022-01-20 |
| Pictures | 0 |
| Listing price | View report |

source: cargurus.co.uk



MOT history

| MOT expiry date | 2024-08-17 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 3 |
| Failed MOT tests | 0 |
| Total advice items | 5 |
| Total items failed | 0 |

| MOT #3 | | 2023-08-17 14:39 |
|-----------|---|------------------|
| MOT test | number | 863142125042 |
| Result | | 🗸 Passed |
| Next expi | ry date | 2024-08-17 |
| Advice | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (| 5.2.3 (d) (i)) |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Front Tyre has a cut but not deep enough to reach the ply or cords | (5.2.3 (d) (i)) |

| MOT #2 | 2022-07-22 10:46 |
|-----------------|------------------|
| MOT test number | 291339477742 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2021-07-28 10:16 |

| MOT test | number | 892053420933 |
|----------|---|--------------|
| Result | | ✓ Passed |
| Advice | Steering column top bearing slightly worn (2.2.2 (b)) | |



Tax & MOT check

| ✓ Taxed | √ MOT | |
|-------------------------------|----------------------------|--|
| Tax due: 1 May 2025 | Expires: 17 August 2024 | |
| Tax status | Valid until 1 May | |
| Days left | 366 | |
| MOT expiry date | 17 August 2024 | |
| Full MOT history | See MOT history | |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--------|
| Date | FET O |
| Category | LAMP |
| Туре | |
| Damage 2 | VAMPLE |
| Date | |
| Category | AMPL |
| Туре | |

Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ********** | |
|--|-------------|
| ACCOUNTS AND A DESCRIPTION OF A DESCRIPR | |
| | |
| And and a second s | |
| ********** | |
| ******** | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VAUXHALL had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |



KU18NVA report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 5 |
| First mileage registration | 2018-08-18 |
| Last registration | 2023-08-17 |
| Complete history | See info |



| Registration #1 | 2018-08-18 | 28 mi |
|-----------------|------------|------------|
| Registration #2 | 2021-07-28 | 2.709 mi |
| Registration #3 | | 11.777 esi |
| Registration #4 | | 11.777 est |
| Registration #5 | | 11.117 mi |





Safety ratings

| NCAP rating | **** | |
|----------------|-----------------|--|
| Adult | 86% | |
| Children | 84% | |
| Pedestrian | 83% | |
| Safety systems | 75% | |
| Overall rating | 83% | |
| Video | see crash video | |



| Dimensions & weight | |
|--|--------------------------|
| Width | 2042 mm |
| Height | 1485 mm |
| Length | 4370 mm |
| Wheel base | 2662 mm |
| Kerb weight | 1233 kg |
| Max. allowed weight | 1845 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 48 I |
| | 48 l Direct Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Direct Injection |
| Fuel tank capacity Fuel delivery Number of doors | Direct Injection 5 |