





report date: 2024-03-28

## General information

Make	AUDI
Model	A2 TDI SE
Colour	Green
Year of manufacture	2001
Top speed	107 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	74 BHP
Max. torque	195 Nm at 2.200 rpm
Engine capacity	1.390 сс
Cylinders	3
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	80.7 mpg
Consumption combined	65.7 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/16



report date: 2024-03-28

# Internet history

## Entry 1

Date 2022-03-09

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/16



RO51FNX report date: 2024-03-28

**MOT** history

MOT expiry date	2023-03-21
MOT pass rate	61 %
MOT passed	17
Failed MOT tests	11
Total advice items	49
Total items failed	30

CarCheck.co.uk page 3/16



report date: 2024-03-28

MOT #28 2023-07-07 13:58

**MOT test number** 664262380117

**Result** X Failed

CarCheck.co.uk page 4/16

Fail Electronic power steering not working (2.6 (c)) Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i)) **Advice** Rear seat backs missing Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Offside Front Position lamp not working (4.2.1 (a) (ii)) Fail Offside Obligatory mirror insecure (3.3 (b) (ii)) **Advice** Front and rear tires of different size Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) **Advice** Reversing lights not working Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Nearside Headlamp lens slightly defective (4.1.1 (b) (i)) Minor Advice Offside Rear Service brake binding but not excessively (1.2.1 (f)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) Fail Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) Advice **Advice** O/s front and rear bumpers damaged Electronic power steering warning lamp indicates a system malfunction (2.6 (a)) Fail **Advice** Both front tires getting low 3mm Fail Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) **Advice** Fuel flap release button not working(release with emergency release leaver) Fail Nearside Obligatory mirror insecure (3.3 (b) (ii)) Offside Headlamp lens slightly defective (4.1.1 (b) (i)) Minor **Advice** Offside Play in steering rack inner joint(s) Fail Offside Headlamp insecure (4.1.1 (c)) Fail Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i))



report date: 2024-03-28

MOT #27

MOT test number

616585008052

Result

Advice Slight play both inner rack ends

**MOT #26** 2022-03-10 11:30 **MOT** test number 352307598848 Result **X** Failed Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) **Advice** Slight play both inner rack ends Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) Advice Offside Front Tyre worn close to legal limit/worn on edge replace soon (5.2.3 (e)) Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b)) Fail Nearside Rear Service brake excessively binding (1.2.1 (f)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge replace soon (5.2.3 (e))

 MOT #25
 2021-01-18 10:35

 MOT test number
 691785665816

 Result
 ✓ Passed

 MOT #24
 2021-01-18 10:35

 MOT test number
 603538290840

 Result
 X Failed

 Pass with rectification
 Offside Rear fog lamp not working (4.5.1 (a) (ii))

CarCheck.co.uk page 5/16



report date: 2024-03-28

MOT test number
986227616306

Result

Advice Offside Front Play in steering rack inner joint(s)

Advice General rear axle corrosion

Advice Nearside Front Play in steering rack inner joint(s)

MOT #22

MOT test number

Result

Advice Play in steering rack inner joint(s)

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #21

MOT test number

893512707556

Result

Advice Play in steering rack inner joint(s)

Pass with rectification Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #20

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Slight play o/s steering rack end

Advice N/s/f tyre worn inner edge

CarCheck.co.uk page 6/16



report date: 2024-03-28

**MOT #19** 2018-01-31 09:57 532972862138 **MOT** test number Result × Failed **Advice** Both front tyres worn inner edges Fail Direction indicator incorrect colour both rear (1.4.A.2f) Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b) Advice Slight play o/s steering rack end **Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #18

MOT test number

532308860676

Result

✓ Passed

MOT #17

MOT test number

Result

Advice

Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

Advice

Rear registration plate delaminated but not likely to be misread (6.3.1d)

Advice

Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT test number

637810026566

Result

Fail Offside Stop lamp not working (1.2.1b)

Advice Rear registration plate delaminated but not likely to be misread (6.3.1d)

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

Advice Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

CarCheck.co.uk page 7/16



report date: 2024-03-28

MOT #15

MOT test number

Result

Advice Rear registration plate delaminated but not likely to be misread (6.3.1d)

MOT test number

Result

Pass with rectification

Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

Advice

Rear registration plate delaminated but not likely to be misread (6.3.1d)

Pass with rectification

Offside Rear Direction indicator incorrect colour (1.4.A.2f)

MOT test number

Result

Notice Under-trays fitted obscuring some underside components

Notice Child seat fitted not allowing full inspection of adult belt

Notice Nearside rear tyre low tread on inner edge

**MOT #12** 2014-06-19 14:45 619470974179 **MOT** test number Result × Failed **Notice** Nearside rear tyre low tread on inner edge **Pass with rectification** Nearside Headlamp aim too high (1.8) **Notice** Under-trays fitted obscuring some underside components **Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a) Notice Child seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 8/16



report date: 2024-03-28

MOT #11	2013-06-04 15:37
MOT test number	778875853101
Result	✓ Passed
MOT #10	2012-08-09 15:51
MOT test number	907522522271
Result	✓ Passed
MOT #9	2011-08-16 14:19
MOT test number	357128421465
Result	✓ Passed
Notice Nearside front coil spring fitted upside-down, but securely located.	

MOT #8	2011-08-15 11:57
MOT test number	796827221293
Result	<b>X</b> Failed
Fail Offside Rear coil spring incomplete (2.4.C.1a)	
<b>Notice</b> Nearside front coil spring fitted upside-down, but securely located.	
Fail Rear registration plate deteriorated (6.3.1d)	

MOT #7	2010-08-16 14:37
MOT test number	630648520208
Result	✓ Passed
MOT #6 2010-08-16 09:51	
MOT test number 62263882021	
Result	<b>X</b> Failed
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

CarCheck.co.uk page 9/16



report date: 2024-03-28

MOT #5	2009-08-18 12:33
MOT test number	212020439218
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #4	2009-08-10 09:50
MOT test number	182252429230
Result	<b>X</b> Failed
Fail Offside Front coil spring incomplete (2.4.C.1a)	
Fail Windscreen washer provides insufficient washer liquid (8.2.3)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #3	2008-08-11 10:02
MOT test number	364114228487
Result	✓ Passed
MOT #2	2007-07-24 09:51
MOT test number	374015007276
Result	<b>✓</b> Passed
MOT #1	2006-08-12 11:03
MOT test number	322464326455
Result	✓ Passed

CarCheck.co.uk page 10/16



report date: 2024-03-28

#### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 12/16



report date: 2024-03-28

Owner	history

*		
For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report I		ve?
THE PARTY OF THE P		
***************************************		
	More info	>
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK NEZ	
Plate since		
	More info	>

CarCheck.co.uk page 13/16



report date: 2024-03-28

#### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 14/16



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2001-09-11
Last registration	2023-07-07
Complete history	See info



Registration #1	2001-09-11	10 mi
Registration #2	2006-08-12	35.461 mi
Registration #3	2007-07-24	41.224 mi
Registration #4	2008-08-11	46.370 mi
Registration #5	2009-08-10	51.587 mi
Registration #6	2009-08-18	51.587 mi
Registration #7	2010-08-16	57.465 mi
Registration #8	2010-08-16	57.465 mi
Registration #9	2011-08-15	62.735 mi
Registration #10	2011-08-16	62.735 mi
Registration #11	2012-08-09	69.026 mi
Registration #12	2013-06-04	70.013 mi
Registration #13	2014-06-19	74.778 mi
Registration #14	2015-06-02	75.415 mi
Registration #15		11.177 mi
Registration #16		11.117 es
Registration #17		11.177 es
Registration #18		11.177 es
Registration #19		11.177 mi
Registration #20		11.777 es
Registration #21		11.177 es
Registration #22		11.117 es
Registration #23		11.177 es
Registration #24		11.177 es
Registration #25		11.177 es
Registration #26		0.00 44
CarCheck.co.uk		page 15/16

Registration #27

Registration #28

More info >

mn.n.n



report date: 2024-03-28

## Car features

50225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Dimensions & weight

Width	1676 mm
Height	1550 mm
Length	3810 mm
Wheel base	2405 mm
Kerb weight	990 kg

# Additional information

Fuel tank capacity	34
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	AMF 123912

CarCheck.co.uk page 16/16