





### General information

Make	VOLVO
Model	S40 S
Colour	Red
Year of manufacture	2002
Top speed	118 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual
Year of manufacture Top speed 0 - 60 mph	2002 118 mph 12.0 seconds

## Engine & fuel consumption

Power	107 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.2 mpg
CO2 emission	184 g/km
CO2 label	I







## Internet history

Entry	1
Date	

2021-10-30

Listing price

Pictures

View report

10



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-08-17
MOT pass rate	95 %
MOT passed	19
Failed MOT tests	1
Total advice items	11
Total items failed	2

MOT #20	2023-08-08 10:06
MOT test number	356115142086
Result	✓ Passed
Next expiry date	2024-08-17
Advice Nearside Rear tyre cracking	
Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1	.11 (c))
Advice Offside Rear tyre cracking	
Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.1	1 (c))

MOT #19	2022-07-25 13:24
MOT test number	473931089293
Result	✓ Passed
MOT #18	2021-08-18 13:48
MOT test number	404512221599
Result	✓ Passed

MOT #17	2020-05-04 10:57
MOT test number	423760074634
Result	✓ Passed



**Advice** Front tyre perishing/cracking at n/s



MOT #16	2019-05-11 11:57
MOT test number	318803362365
Result	✓ Passed
MOT #15	2018-05-02 16:11
MOT test number	634499949803
Result	✓ Passed
Advice Slight drag on o/s front brake	

MOT #14	2018-04-28 12:04
MOT test number	380877671890
Result	🗙 Failed
Advice Slight drag on o/s front brake	
Fail Offside Rear Tyre has ply or cords exposed (4.1.D.1b)	
Fail Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)	
Advice Front tyre perishing/cracking at n/s	

MOT #13	2017-05-31 13:29
MOT test number	862266794260
Result	✓ Passed

MOT #12	2016-06-01 13:22
MOT test number	441122313308
Result	✓ Passed
Advice Nearside Rear brake disc worn, pitted or scored, but not seriou	usly weakened (3.5.1i)





MOT #11		2015-05-27 14:44
MOT test nu	umber	588387845109
Result		✓ Passed
MOT #10		2014-05-19 13:20
MOT test nu	ımber	776929834100
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
MOT #9		2013-05-28 15:03
MOT test nu	umber	675818643167
Result		🗸 Passed
MOT #8		2012-05-31 10.44

MOT #8	2012-05-31 10:44
MOT test number	685042952173
Result	✓ Passed

MOT #7	2011-05-27 10:58
MOT test number	188947641132
Result	✓ Passed

2010-05-28 10:48
594998740199
✓ Passed

MOT #5	2009-05-20 10:54
MOT test number	412440849152
Result	✓ Passed





MOT #4	2008-05-30 16:12
MOT test number	703621158124
Result	✓ Passed
MOT #3	2007-05-31 13:02
MOT test number	642811457161
Result	✓ Passed
MOT #2	2006-05-30 14:03
MOT test number	283620256486
Result	✓ Passed
MOT #1	2005-05-25 10:30
MOT test number	331025645182
Result	✓ Passed



Tax & MOT check

√ Taxed	√ МОТ
<b>Tax due:</b> 1 July 2024	<b>Expires:</b> 17 August 2024
Tax status	Valid until 1 July
Days left	62
MOT expiry date	17 August 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





#### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERM
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

#### Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





## Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

******	
***********	
*******	
******	
***********	
********	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	
Plate since	
Correct registration	
Plate since	





#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2002-05-31
Last registration	2023-08-08
Complete history	<u>See info</u>



20 mi 10.242 mi 11.594 mi 13.068 mi 14.546 mi 15.719 mi 17.317 mi
11.594 mi 13.068 mi 14.546 mi 15.719 mi 17.317 mi
13.068 mi 14.546 mi 15.719 mi 17.317 mi
14.546 mi 15.719 mi 17.317 mi
15.719 mi 17.317 mi
17.317 mi
10 525
18.535 mi
19.743 mi
21.087 mi
22.125 mi
11.777 mil
11.777 mi
11.777 mil
11.777 mi
11.317 mil
11.777 mi
11.777 est
11.777 mi
11.717 mi
11.777 mi
11.717 mi





## Car features

S0225	Air conditioning
\$0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1716 mm
Height	1425 mm
Length	4516 mm
Wheel base	2562 mm
Kerb weight	1280 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number CarCheck.co.uk	B4162863227 page 13/13