





report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE
Colour	Grey
Year of manufacture	2015
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	95 g/km
CO2 label	Α



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2022-02-26

Pictures 4

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

N/I	α		TC:	-	r\/
101	•		115		ıv
	•	Γh			. ,

MOT expiry date	2025-03-14
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	8
Total items failed	5

MOT #10	2024-03-11 12:29
MOT test number	187297668147
Result	✓ Passed
Next expiry date	2025-03-14

MOT #9	2023-02-28 14:21
MOT test number	688767980038
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8	2023-02-28 14:21
MOT test number	865106409867
Result	★ Failed
Advice Nearside Front T	yre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification longer prevents the ingress	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no of dirt clip $(6.1.7 (g) (ii))$

MOT #7	2022-03-15 16:29
MOT test number	834812537746
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

Result

Advice Exhaust mount bracket broke off

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5

MOT test number

2020-06-22 15:44

MOT test number

202067048869

Result

✓ Passed

Advice Surface cracks in both rear tyres

MOT test number

643945333075

Result

Advice Surface cracks in both rear tyres

Fail Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (iii))

MOT #3

MOT test number

692840326844

Result

MOT #2

2019-06-20 08:36

MOT test number

283230299846

Result

Pass with rectification

Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1 2018-06-23 08:16

MOT test number 616824976409

Result ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	14 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12




report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner I	history
---------	---------

For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full		OEN
manus .		

	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		
Current registration	OK ONE	
Flate since		
Current registration	NK NK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-06-23
Last registration	2024-03-11
Complete history	See info



Registration #1	2015-06-23	26 mi
Registration #2	2018-06-23	23.161 mi
Registration #3	2019-06-20	29.785 mi
Registration #4	2019-06-20	29.785 mi
Registration #5	2020-06-22	36.127 mi
Registration #6	2020-06-22	36.127 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFM0107961

CarCheck.co.uk page 12/12