



WN65LRZ

report date: 2024-03-28

General information

Make	MAZDA
Model	MX-5 SE-L NAV
Colour	Red
Year of manufacture	2015
Top speed	133 mph
0 - 60 mph	7.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	158 BHP
Max. torque	200 Nm at 4.600 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.9 mpg
CO2 emission	161 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-08-10
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-08-09
Pictures	24
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-03
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	11
Total items failed	1

MOT #8	2023-09-04 14:00
MOT test number	328370529218
Result	✓ Passed
Next expiry date	2024-09-03

MOT #7	2022-08-11 11:08
MOT test number	963936868804
Result	✓ Passed

MOT #6	2022-08-11 11:08
MOT test number	706463714185
Result	✗ Failed
Pass with rectification Headlamp aim too high P.R.S offside & nearside, adjusted both lamps, no further fault found (4.1.2 (a))	

MOT #5	2021-08-18 09:17
MOT test number	216281798259
Result	✓ Passed

**MOT #4**

2020-10-20 10:27

MOT test number

488808083157

Result

✓ Passed

Advice

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))

Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))

Advice

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))

Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))

MOT #3

2020-10-19 14:02

MOT test number

295129219969

Result

✗ Failed

Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))

MAJOR

Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))

MAJOR

Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))

MAJOR

Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))

MOT #2

2019-10-21 15:11

MOT test number

485317848079

Result

✓ Passed

MOT #1

2018-11-02 15:35

MOT test number

298763775053

Result

CarCheck.co.uk

✓ Passed
page 4/11



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
3 September 2024

Tax status		Valid until 1 September
Days left		124
MOT expiry date		3 September 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	WN65LRZ
Plate since	2019-09-28
Current registration	WN65LRZ
Plate since	2019-09-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-10-31
Last registration	2023-09-04
Complete history	See info



Registration #1	2015-10-31	17 mi
Registration #2	2018-11-02	15.234 mi
Registration #3	2019-10-21	20.274 mi
Registration #4	2020-10-19	23.206 mi
Registration #5	2020-10-20	23.206 mi
Registration #6	2020-10-20	23.206 mi
Registration #7	2020-10-20	23.206 mi
Registration #8	2020-10-20	23.206 mi
Registration #9	2020-10-20	23.206 mi
Registration #10	2020-10-20	23.206 mi
Registration #11	2020-10-20	23.206 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	84%
Children	80%
Pedestrian	93%
Safety systems	64%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1735 mm
Height	1230 mm
Length	3915 mm
Wheel base	2310 mm
Kerb weight	1000 kg
Max. allowed weight	1260 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	PE 30817606