



Mercedes-Benz

UK

HVI2KVT

report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	VITO 110 CDI
Colour	Blue
Year of manufacture	2012
Top speed	98 mph
0 - 60 mph	18.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	250 Nm at 1.400 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.5 mpg
Consumption extra urban	42.8 mpg
Consumption combined	36.2 mpg





Internet history

Entry 1

Date	2021-12-20
Pictures	3
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2022-05-13
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	28
Total items failed	0

MOT #9	2021-05-14 17:07
MOT test number	466039468846
Result	✓ Passed
Next expiry date	2022-05-13
Advice	Bonnet stay missing
Advice	Rear exhaust clamp is missing
Advice	Front number plate is damaged
Advice	Offside front flexi is tight on full lock



MOT #82021-05-14 11:06

MOT test number875816140372

Result

Failed

Advice

Rear exhaust clamp is missing

MAJOR

Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

MAJOR

Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice

Front number plate is damaged

Advice

Offside front flexi is tight on full lock

DANGEROUS

Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MAJOR

Offside Rear Position lamp not working (4.2.1 (a) (ii))

Advice

Bonnet stay missing



<b>MOT #7</b>	2021-04-20 12:19
<b>MOT test number</b>	612272573780
<b>Result</b>	✗ Failed
<b>MAJOR</b> Offside Rear Direction indicator incorrect colour (4.4.3 (a))	
<b>DANGEROUS</b> Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))	
<b>Advice</b>	Front number plate is damaged
<b>Advice</b>	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
<b>Advice</b>	Rear exhaust clamp is missing
<b>MAJOR</b> Exhaust diesel particulate filter shows evidence of tampering. (8.2.2.1 (c))	
<b>MAJOR</b> Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
<b>MAJOR</b> Offside Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))	
<b>Advice</b>	Central exhaust clamp is deteriorated
<b>MAJOR</b> Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	
<b>Advice</b>	Offside front flexible brake hose is stretching on full lock
<b>MAJOR</b> Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))	

<b>MOT #6</b>	2020-04-28 09:48
<b>MOT test number</b>	846562811731
<b>Result</b>	✓ Passed

<b>MOT #5</b>	2019-03-07 10:24
<b>MOT test number</b>	271330809173
<b>Result</b>	✓ Passed

<b>MOT #4</b>	2018-03-01 16:29
<b>MOT test number</b>	621594440232
<b>Result</b>	✓ Passed



MOT #3	2017-02-11 13:28
MOT test number	210031636309
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit inner and outer (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit inner and outer (4.1.E.1)

MOT #2	2016-02-22 16:09
MOT test number	390577472323
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)

MOT #1	2015-03-17 09:07
MOT test number	877956775074
Result	✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
10 January 2024

✕  
MOT

Expired:  
13 May 2022

Tax status	Expired at 10 January 2024
Days left	110 days too late
MOT expiry date	13 May 2022
Full MOT history	<a href="#">See MOT history</a>



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-29
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2012-03-30
Last registration	2021-05-14
Complete history	<a href="#">See info</a>



Registration #1	2012-03-30	20 mi
Registration #2	2015-03-17	68.283 mi
Registration #3	2016-02-22	87.988 mi
Registration #4	2017-02-11	110.655 mi
Registration #5	2018-03-01	139.961 mi
Registration #6	2019-03-07	156.010 mi
Registration #7	2020-05-20	161.277 mi
Registration #8	2020-05-20	161.277 mi
Registration #9	2020-05-20	161.277 mi
Registration #10	2020-05-20	161.277 mi
Registration #11	2021-05-14	161.277 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	65194030430365