





report date: 2024-03-29

### General information

Make	VOLKSWAGEN
Model	TRANSPORTER T28 TDI P/V STARTLINE BMT
Colour	Black
Year of manufacture	2016
Top speed	91 mph
0 - 100 km/h	15.4 seconds
0 - 60 mph	19.7 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	75 kW / 102 HP / 83 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	48.7 mpg
Consumption combined	42.2 mpg
CO2 emission	176 g/km
CO2 label	I



CarCheck.co.uk page 1/11



CV16UPZ

report date: 2024-03-29


### Internet history

#### Entry 2

Date 2021-07-17

Pictures 44

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-07-16	

Pictures 44

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-10-10
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	7
Total items failed	3

MOT #6		2023-09-26 08:37
MOT test	number	475998772480
Result		✓ Passed
Next expi	ry date	2024-10-10
Advice	Nearside Front Play in steering rack inner joint(s)	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5	2022-10-11 13:01
MOT test number	558896632033
Result	✓ Passed
MOT #4	2022-10-10 12:10
MOT test number	497472401569
Result	<b>×</b> Failed
Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))	

CarCheck.co.uk page 3/11



MOT #3 2021-07-28 14:45

**MOT test number** 729801626287

MOT #2 2020-10-30 14:05

MOT test number 577482715613

**Result** ✓ Passed

MOT #1 2019-04-08 09:46

**MOT test number** 542228053245

Result \( \sqrt{Passed} \)

**Advice** Plastic undertrays obscuring some components .

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/11



#### Tax & MOT check



Tax status	Valid until 1 December
Days left	215
MOT expiry date	10 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1

Date

Category

Туре

Damage 2

Category

Date

Type



#### Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
********	
***************************************	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK NE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-03-31
Last registration	2023-09-26
Complete history	See info



Registration #1	2016-03-31	15 mi
Registration #2	2019-04-08	61.256 mi
Registration #3	2020-10-30	82.453 mi
Registration #4		71.777 66
Registration #5		11.777 es
Registration #6		71.777 66
Registration #7		11.777 es
Registration #8		71.777 66
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



### Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	***
Adult	79%
Children	74%
Pedestrian	32%
Safety systems	57%
Overall rating	66%
Video	see crash video



## Dimensions & weight

Width	2283 mm
Height	1990 mm
Length	4892 mm
Wheel base	3400 mm
Kerb weight	1855 kg
Max. allowed weight	2800 kg

### Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	pago 11/11

CarCheck.co.uk page 11/11

Number of seats	3
Number of axles	2
Engine number	CAAA938089