



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D DRIVE SE
Colour	Grey
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	6.6 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-12-08
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-15
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	25
Total items failed	3

MOT #14	2023-12-07 15:51
MOT test number	222144273722
Result	✓ Passed
Next expiry date	2024-12-15
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MOT #13	2023-11-30 13:49
MOT test number	750047623587
Result	✗ Failed
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
DANGEROUS	Offside Rear Anti-roll bar fractured (5.3.3 (b) (ii))

MOT #12	2022-12-16 14:45
MOT test number	519741821828
Result	✓ Passed
Advice	Rear wiper blade split

**MOT #11**

2022-12-15 11:37

MOT test number

975817013131

Result**✗ Failed****Advice** Rear wiper blade split**MAJOR** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #10**

2021-12-15 11:59

MOT test number

523275168205

Result**✓ Passed****Advice** Surface corrosion on vehicle underbody**Advice** Brake disc worn, but not excessively Both rear (1.1.14 (a) (i))**MOT #9**

2021-12-14 17:37

MOT test number

731485151142

Result**✗ Failed****MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Surface corrosion on vehicle underbody**MAJOR** Suspension arm pin or bush excessively worn Both front rear bush (5.3.4 (a) (i))**Advice** Bonnet does not stay in open position**Advice** Brake disc worn, but not excessively Both rear (1.1.14 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #8**

2021-04-21 12:58

MOT test number

399329647707

Result

✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement wish bone rear bush (5.3.4 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement wish bone rear bush (5.3.4 (a) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #7

2019-11-22 14:33

MOT test number

556911276561

Result

✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge inner tread area (5.2.3 (e))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone rear bush (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone rear bush (5.3.4 (a) (i))

MOT #6

2018-07-11 12:20

MOT test number

284519001868

Result

✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5

2017-06-15 10:50

MOT test number

650999717533

Result

✓ Passed

MOT #4

2017-06-15 10:50

MOT test number

614594047804

Result

✗ Failed

Pass with rectification Nearside Front Headlamp not working on dipped beam (1.7.5a)

**MOT #3** 2016-05-19 16:38**MOT test number** 601791864947**Result** ✓ Passed**Advice** Offside Front Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2016-05-19 16:38**MOT test number** 152243723429**Result** ✗ Failed**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2015-05-07 16:27**MOT test number** 218787225165**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
15 December 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	15 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YY12LCL
Plate since	2019-03-29
Current registration	YY12LCL
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-05-22
Last registration	2023-12-07
Complete history	See info



Registration #1	2012-05-22	28 mi
Registration #2	2015-05-07	64.107 mi
Registration #3	2016-05-19	84.083 mi
Registration #4	2016-05-19	84.083 mi
Registration #5	2017-06-15	103.317 mi
Registration #6	2017-06-15	103.317 mi
Registration #7	2018-07-11	118.874 mi
Registration #8	2019-11-22	139.672 mi
Registration #9	2020-05-20	151.277 mi
Registration #10	2020-05-20	151.277 mi
Registration #11	2020-05-20	151.277 mi
Registration #12	2020-05-20	151.277 mi
Registration #13	2020-05-20	151.277 mi
Registration #14	2020-05-20	151.277 mi
Registration #15	2020-05-20	151.277 mi
Registration #16	2023-12-07	151.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1433 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2041867