



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	SLK SLK 200 KOMPRESSOR
Colour	Silver
Year of manufacture	2008
Top speed	144 mph
0 - 60 mph	7.9 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	184 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	34.9 mpg
CO2 emission	196 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-08-10
Pictures	15
Listing price	View report



source: autotrader.co.uk





MOT history

MOT expiry date	2024-08-15
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	20
Total items failed	7

MOT #18	2023-08-04 09:05
MOT test number	803878932808
Result	✓ Passed
Next expiry date	2024-08-15
Advice	Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #17	2022-07-28 12:11
MOT test number	157477735125
Result	✓ Passed

MOT #16	2021-08-16 11:38
MOT test number	171206884298
Result	✓ Passed

MOT #15	2021-03-15 17:34
MOT test number	960020336751
Result	✓ Passed

**MOT #14**

2020-01-31 12:44

MOT test number

723646657048

Result

✓ Passed

Advice

Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice

Offside Front Lower Suspension arm ball joint has slight play rear (5.3.4 (a) (i))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge just below 3mm - Legal limit 1.6 (5.2.3 (e))

MOT #13

2020-01-30 10:43

MOT test number

336807052453

Result

✗ Failed

Advice

Offside Rear Tyre worn close to legal limit/worn on edge just below 3mm - Legal limit 1.6 (5.2.3 (e))

Advice

Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Fail

Offside Rear Brake pipe excessively corroded above diff (1.1.11 (c))

Advice

Offside Front Lower Suspension arm ball joint has slight play rear (5.3.4 (a) (i))

Advice

Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Fail

Nearside Rear Brake pipe excessively corroded above diff (1.1.11 (c))

MOT #12

2019-02-18 17:39

MOT test number

479483069376

Result

✓ Passed

MOT #11

2019-02-18 11:47

MOT test number

928131054379

Result

✗ Failed

Fail

Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail

Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #10** 2018-01-25 11:24**MOT test number** 877248354549**Result** ✓ Passed**Advice** Under trays fitted restricting testers view**MOT #9** 2017-02-20 09:23**MOT test number** 772795862320**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin both sides 2mm (3.5.1g)**Advice** Rear Brake pipe slightly corroded above axle (3.6.B.2c)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)**MOT #8** 2016-02-22 15:02**MOT test number** 451731159736**Result** ✓ Passed**MOT #7** 2015-02-17 11:31**MOT test number** 598018845004**Result** ✓ Passed**MOT #6** 2014-02-10 14:24**MOT test number** 308371744010**Result** ✓ Passed**MOT #5** 2014-02-10 14:24**MOT test number** 187691344089**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #4** 2013-02-12 14:19**MOT test number** 519323643046**Result** ✓ Passed**MOT #3** 2012-02-16 14:04**MOT test number** 456167342064**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #2** 2012-02-15 14:45**MOT test number** 329796942047**Result** ✗ Failed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #1** 2011-07-05 10:34**MOT test number** 196796581138**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
15 August 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	15 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-07-25
Last registration	2023-08-04
Complete history	See info



Registration #1	2008-07-25	29 mi
Registration #2	2011-07-05	27.966 mi
Registration #3	2012-02-15	32.069 mi
Registration #4	2012-02-16	32.069 mi
Registration #5	2013-02-12	39.943 mi
Registration #6	2014-02-10	47.755 mi
Registration #7	2015-02-17	55.041 mi
Registration #8	2016-02-22	61.223 mi
Registration #9	2017-02-20	67.442 mi
Registration #10	2018-01-25	70.970 mi
Registration #11	2019-01-25	75.277 mi
Registration #12	2020-01-25	79.584 mi
Registration #13	2021-01-25	83.891 mi
Registration #14	2022-01-25	88.198 mi
Registration #15	2023-01-25	92.505 mi
Registration #16	2024-01-25	96.812 mi
Registration #17	2025-01-25	101.119 mi
Registration #18	2026-01-25	105.426 mi
Registration #19	2027-01-25	109.733 mi

More info >



Dimensions & weight

Width	1777 mm
Height	1298 mm
Length	4082 mm
Wheel base	2430 mm
Max. allowed weight	1705 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27195431076742