






report date: 2024-03-28

General information

Make	MERCEDES
Model	S-Class S320 CDI
Colour	Silver
Year of manufacture	2006
Top speed	149 mph
0 - 60 mph	7.5 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	540 Nm at 1.600 rpm
Engine capacity	2.987 сс
Cylinders	6
Fuel type	Diesel
Consumption city	24.4 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.0 mpg
CO2 emission	220 g/km
CO2 label	K



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-10-28

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-06-07
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	16
Total items failed	10

MOT #18		2023-06-08 10:38
MOT test	number	885740644325
Result		✓ Passed
Next expi	ry date	2024-06-07
Advice	Brake wear light on dash	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened N/S	/F and O/S/F (1.1.14 (a)

MOT #17	2023-06-08 10:12
MOT test number	653276963562
Result	X Failed
Advice Brake wear light on dash	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened N/S/F and O/S/F (1.1.14 (a) (ii))	
Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))	
Advice Engine management light on dash	

MOT #16	2021-10-08 09:41
MOT test number	791336806135
Result	✓ Passed
Advice Brake pad wear message on the dash	

CarCheck.co.uk page 3/13



MOT #15 2021-09-14 10:59

MOT test number 210587051731

Result X Failed

Advice Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))

Fail Electronic parking brake control missing cables, module assy etc to rear wheels (1.1.6 (d))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Fail Electronic parking brake control defective so that it cannot be satisfactorily operated (1.1.6 (d))

Fail Electronic parking brake warning indicates a malfunction (1.1.6 (e))

Advice Brake pad wear message on dash

MOT #14 2020-09-14 11:24

MOT test number 426579064593

Result Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13 2019-09-13 10:35

MOT test number 495277465890

Result ✓ Passed

MOT #12 2018-08-30 12:46

MOT test number 619005303531

Result

Passed

MOT #11 2017-09-20 15:31

MOT test number 945315904408

Result

Passed

CarCheck.co.uk page 4/13



LK06LXS

report date: 2024-03-28

MOT #10

MOT test number

135508945273

Result

Advice Nearside Front Outer tyre has cut on side wall

MOT #9

MOT test number

Result

MOT #8

MOT test number

2015-10-05 11:49

803387960129

Passed

MOT #8

2014-10-17 09:21

MOT test number

749600094294

Result

Notice Items removed from driver's view prior to test

MOT test number

696409284282

Result

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Notice Items removed from driver's view prior to test

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

 MOT #6
 2013-10-21 14:43

 MOT test number
 499634093232

 Result
 ✓ Passed

CarCheck.co.uk page 5/13



MOT #5

MOT test number

169657142232

Result

Notice Under-trays fitted obscuring some underside components

Notice Engine covers fitted obscuring some components in the engine bay

	,
MOT #4	2011-08-31 15:25
MOT test number	757193741246
Result	√ Passed
MOT #3	2010-09-17 16:55
MOT test number	162710260221
Result	✓ Passed
MOT #2	2009-08-21 17:19
MOT test number	754933339222
Result	✓ Passed
MOT #1	2009-08-20 13:45
MOT test number	130082039233
Result	X Failed
Fail Front brake disc excessively scored (3.5.1h)	
Fail Front brake disc excessively pitted (3.5.1h)	

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	7 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	

AMPLE HAMPLE

Category

Type

Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	NK NE
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-06-22
Last registration	2023-06-08
Complete history	See info



Registration #1	2006-06-22	23 mi
Registration #2	2009-08-20	18.909 mi
Registration #3	2009-08-21	18.911 mi
Registration #4	2010-09-17	30.936 mi
Registration #5	2011-08-31	33.432 mi
Registration #6	2012-09-03	38.660 mi
Registration #7	2013-10-21	42.089 mi
Registration #8	2014-10-16	46.186 mi
Registration #9	2014-10-17	46.186 mi
Registration #10	2015-10-05	46.673 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.79 es
Registration #14		11.777 es
Registration #15		9.79 es
Registration #16		11.777 es
Registration #17		9.79 es
Registration #18		11.777 es
Registration #19		D.777 es
Registration #20		n.m.

More info >

CarCheck.co.uk page 12/13



Safety ratings

NCAP rating	****

Video <u>see crash video</u>



Dimensions & weight

Width	1872 mm
Height	1473 mm
Length	5076 mm
Wheel base	3035 mm
Kerb weight	1965 kg
Max. allowed weight	2550 kg

Additional information

Fuel tank capacity	90 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	64293040246068

CarCheck.co.uk page 13/13