




General information

Make	JAGUAR
Model	S-TYPE D XS
Colour	Green
Year of manufacture	2007
Top speed	143 mph
0 - 60 mph	8.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	206 BHP
Max. torque	435 Nm at 1.900 rpm
Engine capacity	2.720 cc
Cylinders	6
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg
CO2 emission	208 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-06-06
Pictures	23
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-19
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	31
Total items failed	6

MOT #18	2023-06-20 15:46
MOT test number	791758454932
Result	✓ Passed
Next expiry date	2024-06-19
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #17	2023-06-16 11:21
MOT test number	332571840836
Result	✗ Failed
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Offside Rear Direction indicator incorrect colour (4.4.3 (a))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #16**

2022-06-06 08:46

**MOT test number**

538118555708

**Result**

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Engine, floor and sill covers fitted obscuring some components.
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (iii))

**MOT #15**

2021-05-28 12:30

**MOT test number**

970470594346

**Result**

✓ Passed

- Advice** Sill covers fitted . unable to fully inspect outer sills
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Welding carried out unable to fully inspect covered with sealer

**MOT #14**

2021-05-18 11:23

**MOT test number**

385325771502

**Result**

✗ Failed

- Advice** Sill covers fitted . unable to fully inspect outer sills
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))

**MOT #13** 2020-05-22 09:05**MOT test number** 614385788570**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Side repeater insecure (4.4.1 (c) (i))**MOT #12** 2019-05-14 10:52**MOT test number** 414951362096**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2018-05-23 10:17**MOT test number** 882283680689**Result** ✓ Passed**MOT #10** 2017-05-15 15:13**MOT test number** 272528211422**Result** ✓ Passed**Advice** N/s/f tyre wearing on inner edge**Advice** Under tray covers fitted covering components in the underframe**Advice** Engine cover fitted covering components in the engine bay

**MOT #9** 2017-05-15 09:29**MOT test number** 553557930462**Result** ✗ Failed**Advice** Engine cover fitted covering components in the engine bay**Fail** Front registration plate character(s) incorrectly spaced (6.3.4a)**Advice** N/s/f tyre wearing on inner edge**Advice** Under tray covers fitted covering components in the underframe**Fail** Rear registration plate character(s) incorrectly spaced (6.3.4a)**MOT #8** 2016-05-02 13:04**MOT test number** 222003175918**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2015-05-15 14:09**MOT test number** 299875335162**Result** ✓ Passed**MOT #6** 2014-05-07 16:01**MOT test number** 427027324160**Result** ✓ Passed**MOT #5** 2013-04-03 10:47**MOT test number** 795563493018**Result** ✓ Passed**Notice** Nail in nearside rear tyre

**MOT #4** 2012-04-05 11:23**MOT test number** 886986092040**Result** ✓ Passed**MOT #3** 2012-04-04 11:59**MOT test number** 585715292075**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Tyre worn close to the legal limit (4.1.E.1)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #2** 2011-04-06 11:57**MOT test number** 205566491017**Result** ✓ Passed**MOT #1** 2010-04-06 13:41**MOT test number** 110186190098**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
19 June 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	19 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-





Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-12-31
Last registration	2023-06-20
Complete history	<a href="#">See info</a>



Registration #1	2007-12-31	28 mi
Registration #2	2010-04-06	38.223 mi
Registration #3	2011-04-06	41.069 mi
Registration #4	2012-04-04	45.595 mi
Registration #5	2012-04-05	45.595 mi
Registration #6	2013-04-03	52.058 mi
Registration #7	2014-05-07	55.705 mi
Registration #8	2015-05-15	58.225 mi
Registration #9	2016-05-02	60.334 mi
Registration #10	2017-05-15	63.685 mi
Registration #11	2018-05-02	66.334 mi
Registration #12	2019-05-02	69.334 mi
Registration #13	2020-05-02	72.334 mi
Registration #14	2021-05-02	75.334 mi
Registration #15	2022-05-02	78.334 mi
Registration #16	2023-05-02	81.334 mi
Registration #17	2024-05-02	84.334 mi
Registration #18	2025-05-02	87.334 mi
Registration #19	2026-05-02	90.334 mi
Registration #20	2027-05-02	93.334 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2060 mm
Height	1447 mm
Length	4905 mm
Wheel base	2909 mm
Max. allowed weight	2275 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	4
Number of axles	2
Engine number	02224317G