



report date: 2024-03-28

General information

Make	CITROEN
Model	C2 CACHET
Colour	Blue
Year of manufacture	-
Top speed	105 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	72 BHP
Max. torque	118 Nm at 3.300 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2022-01-19
Pictures	16
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT #13	2022-01-06 13:43
MOT test number	708832676573
Result	✓ Passed
Next expiry date	2023-01-31

MOT #12	2022-01-06 13:43
MOT test number	583396635365
Result	✗ Failed
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Pass with rectification	Offside Rear Direction indicator incorrect colour (4.4.3 (a))
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #11	2021-01-28 12:10
MOT test number	802192572844
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #10	2019-07-25 13:50
MOT test number	470705633056
Result	✓ Passed
Advice	Both rear bump stops missing
Advice	Rear Exhaust mounting defective Section in front of box (6.1.2 (a))
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #9** 2018-07-18 10:17**MOT test number** 436452240008**Result** ✓ Passed

- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear exhaust hanger broken but system still supported
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2017-07-06 15:28**MOT test number** 653448065649**Result** ✓ Passed**MOT #7** 2016-07-19 10:53**MOT test number** 419388133679**Result** ✓ Passed

- Advice** Rear tyres getting low and perishing

**MOT #6** 2015-07-09 12:48**MOT test number** 885810295152**Result** ✓ Passed

- Notice** Oil leak
- Notice** O/s/f indicator turning white
- Notice** O/s/f tyre getting low

**MOT #5** 2014-07-01 13:38**MOT test number** 636582384120**Result** ✓ Passed**Notice** Oil leak**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #4** 2013-07-10 09:41**MOT test number** 817111993107**Result** ✓ Passed**Advice** Nearside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-07-10 13:32**MOT test number** 158182692156**Result** ✓ Passed**Notice** Rear tyres worn**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Windscreen wipers slightly deteriorated



MOT #2

2012-07-10 09:00

MOT test number

939392992142

Result

✗ Failed

Notice

Rear tyres worn

Advice

Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Fail

Offside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Notice

Windscreen wipers slightly deteriorated

Advice

Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #1

2011-07-22 11:02

MOT test number

978683501298

Result

✓ Passed

Notice

Front discs are worn thin

Advice

Front Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-07-31
Last registration	2022-01-06
Complete history	<a href="#">See info</a>



Registration #1	2008-07-31	14 mi
Registration #2	2011-07-22	28.721 mi
Registration #3	2012-07-10	36.145 mi
Registration #4	2012-07-10	36.145 mi
Registration #5	2013-07-10	44.481 mi
Registration #6	2014-07-01	55.028 mi
Registration #7	2015-07-09	63.637 mi
Registration #8	2016-07-19	68.038 mi
Registration #9	2016-07-19	68.038 mi
Registration #10	2016-07-19	68.038 mi
Registration #11	2016-07-19	68.038 mi
Registration #12	2016-07-19	68.038 mi
Registration #13	2016-07-19	68.038 mi
Registration #14	2016-07-19	68.038 mi
Registration #15	2016-07-19	68.038 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1659 mm
Height	1477 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	991 kg
Max. allowed weight	1362 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FST35836326