



report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 PURETECH FLAIR
Colour	White
Year of manufacture	2015
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	118 Nm at 2.750 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	107 g/km
CO2 label	B









Internet history

Entry 4

Date	2023-02-17
Pictures	25
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 3




Date	2023-02-16
Pictures	19
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2

Date	2021-02-10
Pictures	16
Listing price	View report



source: [yesauto.com](https://www.yesauto.com)



Entry 1

Date	2021-01-28
------	------------

CarCheck.co.uk

Listing price

[View report](#)



source: [yesauto.com](#)

**MOT history**

MOT expiry date	2025-01-17
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	6
Total items failed	4

MOT #9	2024-01-12 12:16
MOT test number	219199529456
Result	✓ Passed
Next expiry date	2025-01-17
Advice	Front Exhaust mounting defective corroded and split (6.1.2 (a))

MOT #8	2023-01-16 10:00
MOT test number	182468084931
Result	✓ Passed

MOT #7	2022-01-14 19:57
MOT test number	807362102829
Result	✓ Passed
Advice	Oil leak, but not excessive Sump area and front of engine (8.4.1 (a) (i))

MOT #6	2022-01-13 15:27
MOT test number	337208876569
Result	✗ Failed
Advice	Oil leak, but not excessive Sump area and front of engine (8.4.1 (a) (i))
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #5** 2021-01-18 09:46**MOT test number** 161470646724**Result** ✓ Passed**MOT #4** 2020-07-29 13:52**MOT test number** 738995451436**Result** ✓ Passed**MOT #3** 2020-07-29 09:14**MOT test number** 910689508370**Result** ✗ Failed

Fail Nearside Front Tyre has a tear, caused by separation or partial failure of its structure inner wall (5.2.3 (d) (ii))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Offside Front Tyre has a tear, caused by separation or partial failure of its structure inner wall (5.2.3 (d) (ii))

MOT #2 2019-05-14 15:11**MOT test number** 438228390966**Result** ✓ Passed

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #1 2018-03-07 10:58**MOT test number** 618456232195**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
17 January 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	17 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	YR15AEL
Plate since	2015-03-29
Current registration	YR15AEL
Plate since	2015-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2015-03-31
Last registration	2024-01-12
Complete history	See info



Registration #1	2015-03-31	20 mi
Registration #2	2018-03-07	26.247 mi
Registration #3	2019-05-14	30.948 mi
Registration #4	2020-07-29	35.408 mi
Registration #5	2020-07-29	35.409 mi
Registration #6	2021-01-18	36.505 mi
Registration #7	2022-05-20	38.277 mi
Registration #8	2022-05-20	38.277 mi
Registration #9	2022-05-20	38.277 mi
Registration #10	2022-05-20	38.277 mi
Registration #11	2022-05-20	38.277 mi
Registration #12	2022-05-20	38.277 mi
Registration #13	2022-05-20	38.277 mi
Registration #14	2022-05-20	38.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	83%
Children	74%
Pedestrian	33%
Safety systems	40%
Overall rating	67%
Video	see crash video



Dimensions & weight

Width	1729 mm
Height	1480 mm
Length	4157 mm
Wheel base	2595 mm
Kerb weight	965 kg
Max. allowed weight	1500 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B2150067940