



report date: 2024-03-28

General information

Make	VAUXHALL
Model	AGILA DESIGN
Colour	Blue
Year of manufacture	2009
Top speed	106 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	79 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	47.9 mpg
CO2 emission	142 g/km
CO2 label	F





Internet history

Entry 2

Date	2021-08-26
Pictures	1
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-08-25
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-25
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	30
Total items failed	0

MOT #15	2023-07-07 16:13
---------	------------------

MOT test number	572960100880
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-07-25
------------------	------------

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Central Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Central Rear Brake hose has slight corrosion to ferrule both (1.1.12 (f) (i))

**MOT #14**

2023-07-07 09:07

MOT test number

881608043194

Result**✗ Failed**

- MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Central Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Central Rear Brake hose has slight corrosion to ferrule both (1.1.12 (f) (i))

MOT #13

2022-07-08 15:58

MOT test number

648757340372

Result**✓ Passed**

- Advice** Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12** 2022-07-07 13:34**MOT test number** 141133462797**Result** ✗ Failed

- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- MAJOR** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #11 2021-07-26 15:46**MOT test number** 216214608273**Result** ✓ Passed**MOT #10** 2020-07-23 16:07**MOT test number** 849635554548**Result** ✓ Passed**MOT #9** 2020-07-23 15:15**MOT test number** 837565728120**Result** ✗ Failed

- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #8 2019-05-08 15:02**MOT test number** 192246256243**Result** ✓ Passed

- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))



MOT #7	2018-05-17 10:04
---------------	------------------

MOT test number	598164432222
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2017-05-22 08:19
---------------	------------------

MOT test number	926374236253
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2016-05-13 13:52
---------------	------------------

MOT test number	505698132766
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Front Brake pad(s) wearing thin (3.5.1g)
---------------	--

MOT #4	2015-05-13 14:42
---------------	------------------

MOT test number	347783235198
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2014-05-16 12:56
---------------	------------------

MOT test number	229896034137
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	Front wiper blades split at ends but clear screen.
---------------	--

MOT #2	2013-05-13 15:05
---------------	------------------

MOT test number	849023433158
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2012-05-02 11:53
---------------	------------------

MOT test number	425923722176
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
25 July 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	25 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29
Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 CE09XXY
Plate since	2019-09-29
Current registration	 CE09XXY
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-05-05
Last registration	2023-07-07
Complete history	See info



Registration #1	2009-05-05	23 mi
Registration #2	2012-05-02	7.718 mi
Registration #3	2013-05-13	11.278 mi
Registration #4	2014-05-16	15.233 mi
Registration #5	2015-05-13	18.498 mi
Registration #6	2016-05-13	21.858 mi
Registration #7	2017-05-22	24.814 mi
Registration #8	2018-05-17	27.181 mi
Registration #9	2019-05-08	29.755 mi
Registration #10	2020-05-20	31.377 mi
Registration #11	2021-05-20	33.077 mi
Registration #12	2022-05-20	34.777 mi
Registration #13	2023-05-20	36.477 mi
Registration #14	2024-05-20	38.177 mi
Registration #15	2025-05-20	39.877 mi
Registration #16	2026-05-20	41.577 mi
Registration #17	2027-05-20	43.277 mi
Registration #18	2028-05-20	44.977 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	1040 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	1150820