





General information

| Make | PEUGEOT |
|---------------------|----------------|
| Model | 207 HDI ACTIVE |
| Colour | Black |
| Year of manufacture | 2011 |
| Top speed | 112 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 92 BHP |
|-------------------------|---------------------|
| Max. torque | 230 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 53.3 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 64.2 mpg |
| CO2 emission | 110 g/km |
| CO2 label | В |





Internet history

Entry 2

Date Pictures 2021-07-14

11

Listing price

-

View report



source: autotrader.co.uk

| Entry 1 | |
|---------------|-------------|
| Date | 2021-06-08 |
| Pictures | 11 |
| Listing price | View report |
| | |



source: autotrader.co.uk









MOT history

| MOT expiry date | 2023-11-21 |
|--------------------|------------|
| MOT pass rate | 69 % |
| MOT passed | 9 |
| Failed MOT tests | 4 |
| Total advice items | 16 |
| Total items failed | 10 |

| MOT #13 | 2022-11-22 14:07 |
|------------------|------------------|
| MOT test number | 473348898736 |
| Result | ✓ Passed |
| Next expiry date | 2023-11-21 |

| MOT #12 | | 2022-11-22 14:07 |
|-------------------------|---|------------------|
| MOT test number | | 341427490664 |
| Result | | 🗙 Failed |
| Pass with rectification | Offside Front Position lamp not working (4.2.1 (a) (ii)) | |
| Pass with rectification | Nearside Front Position lamp not working (4.2.1 (a) (ii)) | |

| MOT #11 | 2021-11-09 13:31 |
|-----------------|------------------|
| MOT test number | 716260289344 |
| Result | ✓ Passed |



| AK60 | YCS |
|--------------|------------|
| report date: | 2024-03-29 |

| MOT #2 | LO | 2021-11-09 10:37 |
|--------|--|------------------|
| MOT te | st number | 993006963243 |
| Result | | 🗙 Failed |
| Fail | Nearside Front Position lamp not working (4.2.1 (a) (ii)) | |
| Fail | Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (| 4.7.1 (b) (ii)) |
| Fail | Nearside Front Road wheel fixing missing (5.2.1 (a) (i)) | |
| Fail | Offside Front Position lamp not working (4.2.1 (a) (ii)) | |
| Fail | Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) | |
| Fail | Offside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i)) | |

| MOT #9 | | 2020-10-29 10:45 |
|----------|--|------------------|
| MOT test | number | 272400908385 |
| Result | | ✓ Passed |
| Advice | Offside Rear Child Seat fitted not allowing full inspection of adult belt | |
| Advice | Nearside Rear Child Seat fitted not allowing full inspection of adult belt | |

| MOT #8 | 2019-04-29 12:41 |
|---|------------------|
| MOT test number | 841862740877 |
| Result | ✓ Passed |
| Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt | |

| MOT #7 | 2019-04-29 11:02 |
|---|------------------|
| MOT test number | 466174860523 |
| Result | 🗙 Failed |
| Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b)) | |
| Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt | |





| MOT #6 | | 2018-03-20 15:54 |
|------------|--|------------------|
| MOT test ı | number | 628654695526 |
| Result | | ✓ Passed |
| Advice | Nearside Rear Child Seat fitted not allowing full inspection of adult belt | |
| MOT #5 | | 2017-03-21 12:42 |
| MOT test ı | number | 656053698219 |
| Result | | ✓ Passed |
| Advice | Advise swap nearside front tyre to rear. | |
| Advice | Offside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Emissions test passed as readings too low to register. | |
| Advice | Nearside Rear Child Seat fitted not allowing full inspection of adult belt | |

| MOT #4 | | 2017-03-21 11:15 |
|----------|--|------------------|
| MOT test | number | 579934189050 |
| Result | | 🗙 Failed |
| Advice | Advise swap nearside front tyre to rear. | |
| Advice | Nearside Rear Child Seat fitted not allowing full inspection of adult belt | |
| Advice | Offside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Emissions test passed as readings too low to register. | |
| Fail No | earside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) | |





| MOT #3 | 2016-03-29 08:17 |
|--|------------------|
| MOT test number | 898638827650 |
| Result | ✓ Passed |
| Advice Both Front Tyres Worn On Outer Edge Advice Parking brake lever has little reserve travel (3.1.6b) Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| MOT #2 | 2015-03-30 18:24 |
| MOT test number | 799329485053 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2014-01-03 08:21 |

| MOT test number | 998953804067 |
|-----------------|--------------|
| Result | ✓ Passed |





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---|
| Date | |
| Category | 4. DEM PE |
| Туре | |
| Damage 2 | Annet |
| Date | No. Contraction of the second |
| Category | AMP |
| Туре | |

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 6.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 11 711 |





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ****** | |
|--|-------------|
| ********** | |
| ******* | |
| ****** | |
| ********** | |
| ******* | |
| | More info > |
| Plate changes | |
| See in this check if this PEUGEOT had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 16 |
| First mileage registration | 2011-01-29 |
| Last registration | 2022-11-22 |
| Complete history | See info |



| Registration #1 | 2011-01-29 | 18 mi |
|--|------------|--|
| Registration #2 | 2014-01-03 | 28.473 mi |
| Registration #3 | 2015-03-30 | 36.462 mi |
| Registration #4 | 2016-03-29 | 44.185 mi |
| Registration #5 | 2017-03-21 | 50.377 mi |
| Registration #6 | 2017-03-21 | 50.377 mi |
| Registration #7 | 2018-03-20 | 63.017 mi |
| Registration #8 | 2019-04-29 | 74.425 mi |
| | | |
| Registration #9 | | 11.777 esi |
| Registration #9 Registration #10 | | 11.227 est |
| - | | 01,000 est 01,000 est 01,000 est |
| Registration #10 | | 01,000 est 01,000 est 01,000 est 01,000 est |
| Registration #10 Registration #11 | | 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est |
| Registration #10 Registration #11 Registration #12 | | 00,000 e60 01,000 e60 01,000 e60 01,000 e60 01,000 e60 01,000 e60 01,000 e60 |
| Registration #10 Registration #11 Registration #12 Registration #13 | | 00,000 46 0,000 46 0,000 46 0,000 46 0,000 46 0,000 46 0,000 46 |

More info >





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| S0501 | |
| 50566 | |
| 50567 | |
| S0569 | |

Safety ratings

NCAP rating

Video

**** see crash video



| Dimensions & weight | |
|------------------------|------------------|
| Width | 1815 mm |
| Height | 1498 mm |
| Length | 4276 mm |
| Wheel base | 2608 mm |
| Kerb weight | 1410 kg |
| Max. allowed weight | 1800 kg |
| Additional information | |
| Fuel tank capacity | 60 I |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

Number of seats CarCheck.co.uk

| Number of axles | 2 |
|-----------------|-------------|
| Engine number | JBEE0019176 |