





report date: 2024-03-28

General information

Make	VOLVO
Model	V50 R-DESIGN EDITION
Colour	Blue
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Petrol
Consumption city	26.2 mpg
Consumption extra urban	49.6 mpg
Consumption combined	37.2 mpg
CO2 emission	176 g/km
CO2 label	I



CarCheck.co.uk page 1/12



Internet history

Entry 1


Date 2022-02-16


Pictures 38

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-02-22
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	7
Total items failed	3

MOT #15	2024-02-23 09:07
MOT test number	131367601217
Result	✓ Passed
Next expiry date	2025-02-22
Advice Nearside Front Play in steering rack inner joint(s)	

MOT #14	2023-01-31 10:30
MOT test number	231351756995
Result	✓ Passed
MOT #13	2022-02-19 10:59
MOT test number	361046152190
Result	✓ Passed
MOT #12	2021-04-20 10:17
MOT test number	355622463185
Result	✓ Passed

MOT #11	2020-05-12 14:32
MOT test number	642169212016
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #10 2020-05-11 08:32

MOT test number 668852262892

Result X Failed

Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear rear washer not working

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #9 2019-03-27 12:13

MOT test number 248762642964

Result ✓ Passed

MOT #8 2019-03-27 09:01

MOT test number 577581425255

Result X Failed

Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Front Brake pad(s) wearing thin both front (1.1.13 (a) (ii))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2018-04-25 07:50

MOT test number 813291372073

MOT #6 2017-05-23 08:56

MOT test number 898304769323

Result ✓ Passed

CarCheck.co.uk page 4/12



MOT #5 2016-05-25 13:26

MOT test number 807455028041

MOT #4 2016-05-25 08:53

MOT test number 380854287342

Result X Failed

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 205/50/17 (4.1.D.1a)

Advice Parking brake lever has little reserve travel (3.1.6b)

MOT #3 2015-06-17 09:39

MOT test number 235798665418

MOT #2 2014-06-19 15:11

MOT test number 786350174159

Result ✓ Passed

MOT #1 2014-05-03 10:32

MOT test number 688883524109

Result
✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	22 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	1
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when miscory	
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte at Info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-06-17
Last registration	2024-02-23
Complete history	See info



Registration #1	2011-06-17	17 mi
Registration #2	2014-05-03	14.385 mi
Registration #3	2014-06-19	15.210 mi
Registration #4	2015-06-17	20.628 mi
Registration #5	2016-05-25	22.893 mi
Registration #6	2016-05-25	22.893 mi
Registration #7	2017-05-23	27.566 mi
Registration #8	2018-04-25	32.591 mi
Registration #9	2019-03-27	36.051 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.177 mi

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1379 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	55 I	
Fuel delivery	Multi-Point Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5 page 1	2/12

Number of axles2Engine number1045425