



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	VERSO VALVEMATIC TR
Colour	Blue
Year of manufacture	2010
Top speed	115 mph
0 - 60 mph	11.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	132 BHP
Max. torque	160 Nm at 4.400 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	158 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-08-27
Pictures	31
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-08
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	32
Total items failed	2

MOT #14	2023-10-09 09:19
MOT test number	833211045890
Result	✓ Passed
Next expiry date	2024-10-08
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front Tyre slightly damaged/cracking or perishing both side (5.2.3 (d) (ii))

MOT #13	2022-10-07 09:09
MOT test number	619160845734
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12	2022-10-07 09:09
MOT test number	882367126276
Result	✗ Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Pass with rectification	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #11**

2021-10-09 10:27

MOT test number

483478030678

Result

✓ Passed

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #10

2021-10-09 10:27

MOT test number

767592792369

Result

✗ Failed

Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Pass with rectification Front Headlamp aim too low (4.1.2 (a))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #9**

2020-12-10 15:02

MOT test number

881529879852

Result

✓ Passed

- Advice** Offside Front Upper Anti-roll bar: ball joint dust cover leaking
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Nearside Front Track rod end: ball joint dust cover leaking
- Advice** Nearside Front Suspension arm: ball joint dust cover leaking
- Advice** Nearside Front Upper Anti-roll bar: ball joint dust cover leaking
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Offside Front Track rod end: ball joint dust cover leaking
- Advice** Offside Front Suspension arm: ball joint dust cover leaking
- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #8

2019-12-31 11:59

MOT test number

654397871969

Result

✓ Passed

- Advice** Nearside Front ball joint loosing grease
- Advice** Offside Front ball joint loosing grease

MOT #7

2019-01-16 15:27

MOT test number

784634113164

Result

✓ Passed

- Advice** Offside Front Upper ball joint dust cover starting to perish
- Advice** Nearside Front Lower ball joint dust cover starting to perish



MOT #6	2018-01-16 10:17
MOT test number	843338273111
Result	✓ Passed
MOT #5	2017-01-17 13:28
MOT test number	431106175257
Result	✓ Passed
MOT #4	2016-01-07 12:18
MOT test number	771245634470
Result	✓ Passed
MOT #3	2015-01-06 10:57
MOT test number	205896305046
Result	✓ Passed
MOT #2	2014-01-23 15:43
MOT test number	349313024083
Result	✓ Passed
MOT #1	2013-01-23 11:40
MOT test number	945453923037
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
8 October 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	8 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-01-25
Last registration	2023-10-09
Complete history	See info



Registration #1	2010-01-25	8 mi
Registration #2	2013-01-23	27.831 mi
Registration #3	2014-01-23	37.003 mi
Registration #4	2015-01-06	44.930 mi
Registration #5	2016-01-07	52.401 mi
Registration #6	2017-01-17	59.061 mi
Registration #7	2018-01-16	65.344 mi
Registration #8	2019-01-16	72.136 mi
Registration #9	2020-01-20	78.377 mi
Registration #10	2021-01-20	84.618 mi
Registration #11	2022-01-20	90.859 mi
Registration #12	2023-01-20	97.100 mi
Registration #13	2024-01-20	103.341 mi
Registration #14	2025-01-20	109.582 mi
Registration #15	2026-01-20	115.823 mi
Registration #16	2027-01-20	122.064 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	75%
Pedestrian	69%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1620 mm
Length	4440 mm
Wheel base	2780 mm
Kerb weight	1505 kg
Max. allowed weight	2125 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Engine number

1ZRU298322