





#### General information

Make	FIAT
Model	DOBLO MULTIJET ELEGANZA
Colour	Red
Year of manufacture	2012
Top speed	111 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	135 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.956 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	49.6 mpg
CO2 emission	150 g/km
CO2 label	F







# Internet history

Entry 1 Date

Pictures

2022-01-13

67

Listing price

View report









source: autotrader.co.uk



### MOT history

MOT expiry date	2024-12-29
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	33
Total items failed	8

MOT #12	2023-12-08 17:43
MOT test number	987225745504
Result	✓ Passed
Next expiry date	2024-12-29

MOT #11	2022-12-30 17:02
MOT test number	125035544913
Result	✓ Passed
Advice Central Rear Engine mounting damaged but not to excess (6.1.8 (a) (i))	

MOT #1	0	2022-12-03 16:44
MOT tes	st number	778654748400
Result		🗙 Failed
Fail	Offside Front Macpherson strut top bush or bearing has excessive wear or free p	olay (5.3.4 (a) (i))
Fail	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
<b>Fail</b> (1.1.21	Offside Front Brake inadequately mounted stick on weight in the road wheel rub (c))	bing onto the calliper
Fail	Offside Rear Service brake excessively binding (1.2.1 (f))	
Fail	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Advice	Central Rear Engine mounting damaged but not to excess deteriorated (6.1.8	8 (a) (i))





MOT #9		2021-11-27 11:44
MOT test	number	669371532280
Result		✓ Passed
MOT #8		2020-12-04 16:38
MOT test	number	271847342796
Result		Passed
Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))		
Advice	Under trays and engine covers fitted obscuring full view of inspection.	

MOT #7	2019-06-13 08:30
MOT test number	396054368101
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor Nearside Front Side repeater lens defective which has no effect on emitted li	ight (4.4.1 (b) (i))
Advice Offside Front top shocker bearing worn	





MOT #6		2018-01-25 08:58
MOT test	number	737913299891
Result		✓ Passed
Advice	Both front tyres worn on inner edges	
<b>Advice</b> (3.5.1i)	Front brake disc worn, pitted or scored, but not seriously weakened both worn a	and corroded
Advice	Nsr handbrake cable casing deteriorated	
Advice	Nearside rear parking (secondary) brake grabbing slightly (3.7.B.6b)	
Advice	Nearside Front Seat belt cut but webbing not significantly weakened (5.2.2a)	
Advice	Clutch pedal rubber missing	
Advice	Items removed from driver's view prior to test	
Advice	Exhaust backbox outer casing corroded	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Front brake fluctuating, but not excessively both (3.7.B.3)	



MOT #5	2018-01-22 10:23
MOT test number	561839576541
Result	🗙 Failed
Fail Offside Front coil spring broken (2.4.C.1a)	
Advice Nsr handbrake cable casing deteriorated	
Advice Nearside Front Seat belt cut but webbing not significantly weakened (5.2.2a)	
Advice Items removed from driver's view prior to test	
Advice Front Brake pad(s) wearing thin (3.5.1g)	
Advice Clutch pedal rubber missing	
Advice Front brake fluctuating, but not excessively both (3.7.B.3)	
Advice Exhaust backbox outer casing corroded	
Fail Offside Front Suspension arm rubber bush deteriorated resulting in excessive mover	nent (2.4.G.2)
Advice Front brake disc worn, pitted or scored, but not seriously weakened both worn ar (3.5.1i)	id corroded
Advice Nearside rear parking (secondary) brake grabbing slightly (3.7.B.6b)	
Advice Both front tyres worn on inner edges	

MOT #4	2017-01-06 16:08
MOT test number	585052270246
Result	✓ Passed

MOT #3	2016-	05-26 13:56
MOT test n	number 252	2227241177
Result		🗸 Passed
Advice Advice (2.4.G.2)	Nearside Front Seat belt stitching slightly frayed (5.2.2b) Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive m	ovement

**DN12TGO** 

report date: 2024-03-28





MOT #2		2016-05-25 11:48
MOT test	number	663314272992
Result		🗙 Failed
Advice	Nearside Front Tyre worn close to the legal limit raised tread type (4.1.E.1)	
<b>Advice</b> (2.4.G.2)	Offside Front Suspension arm rubber bush deteriorated but not resulting in	excessive movement
Advice	Nearside Front Seat belt stitching slightly frayed (5.2.2b)	
Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)		
MOT #1		2015 OF 10 14.52

MOT #1	2015-05-18 14:52
MOT test number	859108635111
Result	✓ Passed



Tax & MOT check

✓ Taxed	✓ MOT Expires:
Tax status	29 December 2024 Valid until 1 November
Days left	187
MOT expiry date	29 December 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Duniuge 2	E E E E
Date	J.
Category	amer
Туре	

#### Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





### Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

************	
*******	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Number of plates Carnet registration	
Number of plates Correct registration Plate since	
Number of plates Correct registration Plate since Correct registration	
Number of plates Current registration Plate since Current registration Plate since	8000-20-20





#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-05-31
Last registration	2023-12-08
Complete history	See info



Registration #1	2012-05-31	29 mi
Registration #2	2015-05-18	17.894 mi
Registration #3	2016-05-25	26.668 mi
Registration #4	2016-05-26	26.668 mi
Registration #5	2017-01-06	30.194 mi
Registration #6	2018-01-22	45.135 mi
Registration #7	2018-01-25	45.135 mi
Registration #8		11.777 esi
Registration #9		11.777 est
Registration #10		
		11.117 au
Registration #11		11.777 es
-		01,000 est 01,000 est 01,000 est
Registration #11		01,000 est 01,000 est 01,000 est 01,000 est





#### Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1832 mm
Height	1845 mm
Length	4390 mm
Wheel base	2755 mm
Kerb weight	1450 kg
Max. allowed weight	2230 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 14/14

Number of axles	2
Engine number	6762800