



SG09UWK

report date: 2024-03-29

General information

Make	MAZDA
Model	3 TAKARA
Colour	Black
Year of manufacture	2009
Top speed	114 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	162 g/km
CO2 label	G





## MOT history

MOT expiry date	2025-03-27
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	18
Total items failed	7

MOT #11 2020-10-20 15:02

MOT test number 122280175741

Result ✗ Failed

- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Note there is a bearing noise from around the auxiliary belt area.
- Fail** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

MOT #10 2019-04-25 14:06

MOT test number 149011439594

Result ✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #9** 2018-06-01 10:41**MOT test number** 558218434066**Result** ✓ Passed**MOT #8** 2018-06-01 10:41**MOT test number** 972026560953**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on main beam (4.1.1 (a) (ii))**MOT #7** 2017-05-04 15:00**MOT test number** 897599008809**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement  
Rearmost bush (2.4.G.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement  
Rearmost bush. (2.4.G.2)**MOT #6** 2017-05-04 10:46**MOT test number** 942034446877**Result** ✗ Failed**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement  
Rearmost bush (2.4.G.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement  
Rearmost bush. (2.4.G.2)

**MOT #5** 2016-05-04 12:46**MOT test number** 402920228085**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)**MOT #4** 2015-03-04 13:09**MOT test number** 989453065092**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-03-07 16:17**MOT test number** 745916964090**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2013-03-09 12:38**MOT test number** 727338363044**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2012-03-06 15:20**MOT test number** 677886762034**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
27 March 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	336
<b>MOT expiry date</b>	27 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-




Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2009-03-03
Last registration	2020-10-20
Complete history	<a href="#">See info</a>



Registration #1	2009-03-03	9 mi
Registration #2	2012-03-06	18.736 mi
Registration #3	2013-03-09	25.401 mi
Registration #4	2014-03-07	35.512 mi
Registration #5	2015-03-04	42.677 mi
Registration #6	2016-05-04	57.041 mi
Registration #7	2016-05-04	57.041 mi
Registration #8	2016-05-04	57.041 mi
Registration #9	2016-05-04	57.041 mi
Registration #10	2016-05-04	57.041 mi
Registration #11	2016-05-04	57.041 mi
Registration #12	2016-05-04	57.041 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1755 mm
Height	1465 mm
Length	4440 mm
Wheel base	2640 mm
Kerb weight	1275 kg
Max. allowed weight	1725 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z6 733311