





report date: 2024-03-29

General information

Make	MAZDA
Model	5 TS2
Colour	Blue
Year of manufacture	2010
Top speed	134 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	155 BHP
Max. torque	193 Nm at 4.500 rpm
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	53.3 mpg
Consumption combined	40.9 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2022-03-13

Pictures 28

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

LV60UOW report date: 2024-03-29

MOT expiry date	2023-09-08
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	11
Total items failed	2

MOT #14	2022-09-09 13:17
MOT test number	583598906238
Result	✓ Passed
Next expiry date	2023-09-08
Advice Suspension arm pin or bush worn but not resulting in excessive	ve movement both front (5.3.4 (a) (i))

MOT #13	2022-09-09 08:45
MOT test number	240293472995
Result	× Failed
Advice Suspension arm pin or bush worn but not resulting in excessive movements Fail Registration plate does not conform to the specified requirements both (0.1)	

MOT #12	2021-09-03 08:08
MOT test number	638126030344
Result	✓ Passed
MOT #11	2020-09-08 14:41
MOT test number	637446220435
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #10	20	19-09-05 13:16
MOT test	number	297817751948
Result		✓ Passed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	4 (a) (ii))
Advice	Brake pad(s) wearing thin all fronts (1.1.13 (a) (ii))	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))
Advice	Brake pad(s) wearing thin all rears (1.1.13 (a) (ii))	
Advice	Offside Front tyre inner sidewall damaged	

MOT #9	2018-08-28 10:12
MOT test number	575966025090
Result	✓ Passed
MOT #8	2017-09-05 10:32
MOT test number 987495571	
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #7	2016-08-30 09:02
MOT test number	577215709272
Result	✓ Passed
MOT #6	2015-09-08 11:44
MOT test number	717053424232
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #5 2015-09-07 14:39

MOT test number 480178419154

Result X Failed

Advice N/s/f tyre perished

(2.4.G.2)

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #4 2015-04-08 14:48

MOT test number 235408395007

Result \(\sqrt{Passed} \)

MOT #3 2015-01-05 17:00

MOT test number 866425805000

Result ✓ Passed

MOT #2 2014-09-12 15:52

MOT test number 909745654232

Result ✓ Passed

MOT #1 2013-12-09 13:06

MOT test number 686603543308

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



X MOT

Tax expired: 13 July 2023

Expired: 8 September 2023

Tax status	Expired at 13 July 2023
Days left	292 days too late
MOT expiry date	8 September 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



furthe scinors

LV60UOW

report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this MAZDA had different number plates. about of pliates

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-12-30
Last registration	2022-09-09
Complete history	See info



Registration #1	2010-12-30	19 mi
Registration #2	2013-12-09	24.910 mi
Registration #3	2014-09-12	30.177 mi
Registration #4	2015-01-05	30.183 mi
Registration #5	2015-04-08	30.254 mi
Registration #6	2015-09-07	35.001 mi
Registration #7	2015-09-08	35.001 mi
Registration #8	2016-08-30	45.422 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		D.777 es
Registration #15		11.777 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 11/12



report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	77%
Children	81%
Pedestrian	49%
Safety systems	71%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1440 mm
Length	4755 mm
Wheel base	2725 mm
Kerb weight	1435 kg
Max. allowed weight	1955 kg

Additional information

Fuel tank capacity	64 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LF 20316606

CarCheck.co.uk page 12/12