





report date: 2024-03-28

#### General information

Make	NISSAN
Model	CUBE 16V
Colour	White
Year of manufacture	2010
Top speed	109 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	109 BHP
Max. torque	153 Nm at 4.400 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	151 g/km
CO2 label	G



CarCheck.co.uk page 1/13



## Internet history

#### Entry 1

Date 2022-04-15

Pictures 14

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



## MOT history

MOT expiry date	2024-06-19
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	16
Total items failed	4

MOT #15		2023-06-05 11:02
MOT test	number	985362916067
Result		✓ Passed
Next expi	y date	2024-06-19
Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))		
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11	(c))

MOT #14		2022-06-20 10:56
MOT test	number	522557112556
Result		✓ Passed
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #13		2021-10-05 10:12
MOT test	number	313485197847
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



**MOT #12** 2021-10-05 10:12

**MOT test number** 565644811686

Result X Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Pass with rectification** Nearside Front Tyre(s) with different aspect ratios are fitted on the same axle. (5.2.3 (b))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2020-10-08 08:51

**MOT test number** 214752376151

**Result** 
✓ Passed

**MOT #10** 2020-10-08 08:51

**MOT test number** 792712549730

Result X Failed

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #9** 2019-09-26 08:59

**MOT test number** 129523262635

**Result** ✓ Passed

MOT #8 2019-09-20 15:08

MOT test number 292093455018

**Result** ★ Failed

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #7** 2018-09-15 08:08

**MOT test number** 569828131896

Result 

Passed

CarCheck.co.uk page 4/13



MOT #6 2017-10-12 15:22

**MOT test number** 165237579009

**Result** 
✓ Passed

MOT #5 2017-10-11 13:16

**MOT test number** 447556152894

Result X Failed

**Advice** Front disc's corroded Rear pads getting low n/s/r tyre deteriorated

**Advice** Exhaust has a minor leak of exhaust gases Rear (7.1.2)

**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

**MOT #4** 2016-11-30 10:07

**MOT test number** 214031491166

MOT #3 2015-12-02 09:22

MOT test number 450834787213

Result 

Passed

**Advice** Offside Rear Nail in tyre.

**Advice** Internal headlight adjuster moved to zero.

**Advice** Nearside Rear Child seat fitted not allowing full inspection of seatbelt.

MOT #2 2014-12-05 10:23

**MOT test number** 777759534309

**Notice** Child seat fitted not allowing full inspection of adult belt

**Notice** N/S Wiper blade worn but still clearing screen effectively

CarCheck.co.uk page 5/13



**MOT #1** 2013-11-27 09:17

**MOT test number** 506211633304

CarCheck.co.uk page 6/13



### Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	19 June 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



<b>O</b>	history
IWADAL	
	IIISLUIV

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	
HARMAN CONTRACTOR CONT	
THE STREET STREE	
***************************************	
	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	ZIN UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



## Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-12-24
Last registration	2023-06-05
Complete history	See info



Registration #1	2010-12-24	22 mi
Registration #2	2013-11-27	21.650 mi
Registration #3	2014-12-05	25.412 mi
Registration #4	2015-12-02	29.036 mi
Registration #5	2016-11-30	32.975 mi
Registration #6	2017-10-11	36.531 mi
Registration #7	2017-10-12	36.533 mi
Registration #8	2018-09-15	41.278 mi
Registration #9	2019-09-20	47.836 mi
Registration #10		77,777 44
Registration #11		71.777 es
Registration #12		
3		11.117 au
Registration #13		11.777 es
		11.777 es
Registration #13		11.777 es 11.777 es 11.777 es
Registration #13 Registration #14		11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 12/13



### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Adult	83%
Children	64%
Pedestrian	56%
Safety systems	84%
Overall rating	74%
Video	see crash video



## Dimensions & weight

Width	1695 mm
Height	1680 mm
Length	3980 mm
Wheel base	2530 mm
Kerb weight	1230 kg
Max. allowed weight	1700 kg

# Additional information

Fuel tank capacity	52 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles 2
Engine number 264020