

Ford



General information

| Make | FORD |
|---------------------|------------------------------|
| Model | TRANSIT 310 TREND TDCI KOMBI |
| Colour | White |
| Year of manufacture | 2014 |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 98 BHP | 0 < 101 A | |
|-------------------------|----------|-------------|--------|
| Engine capacity | 2.198 cc | 101 - 120 B | |
| Cylinders | 4 | 121 - 140 E | |
| Fuel type | Diesel | 141 - 165 | |
| Consumption city | 38.7 mpg | 166 - 185 | |
| Consumption extra urban | 46.3 mpg | 186 - 225 | , J |
| Consumption combined | 43.5 mpg | 225+ | |
| CO2 emission | 168 g/km | | |
| CO2 label | Н | | |



Internet history

Entry 3

Date

Pictures

Listing price

2023-03-31

18

View report




source: cargurus.co.uk

| Entry 2 | |
|---------------|-------------|
| Date | 2023-03-30 |
| Pictures | 17 |
| Listing price | View report |
| | |









source: autotrader.co.uk

Entry 1

| Date | 2021-10-21 |
|---------------|-------------|
| Pictures | 12 |
| Listing price | View report |



WKK, T-Vans, co.uk

source: cargurus.co.uk



MOT history

| MOT expiry date | 2024-05-31 |
|--------------------|------------|
| MOT pass rate | 69 % |
| MOT passed | 9 |
| Failed MOT tests | 4 |
| Total advice items | 14 |
| Total items failed | 7 |

| MOT #13 | 2023-06-01 16:57 |
|------------------|------------------|
| MOT test number | 965356393252 |
| Result | ✓ Passed |
| Next expiry date | 2024-05-31 |

| MOT #12 | 2022-10-08 11:55 |
|-----------------|------------------|
| MOT test number | 285995150884 |
| Result | ✓ Passed |

| MOT #11 | 2021-10-20 13:46 |
|-----------------|------------------|
| MOT test number | 173368129538 |
| Result | ✓ Passed |

| MOT #10 | 2020-07-20 13:56 |
|---|-----------------------------|
| MOT test number | 988384061450 |
| Result | ✓ Passed |
| Advice Offeide Front Soat bolt webbing slightly damaged or fraved soat be | It wobbing starting to fray |

Advice Offside Front Seat belt webbing slightly damaged or frayed seat belt webbing starting to fray (7.1.2 (b) (ii))





| MOT #9 | 2020-07-17 12:28 |
|--|------------------------------|
| MOT test number | 982263125446 |
| Result | 🗙 Failed |
| Advice Offside Front Seat belt webbing slightly damaged or frayed seat belt we (7.1.2 (b) (ii)) | bbing starting to fray |
| Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to r cut in tread to cords (5.2.3 (d) (i)) | reach the ply or cords has |
| Minor Nearside Front Drive shaft joint constant velocity boot severely deteriora (6.1.7 (g) (i)) | ted cv boot perishing |
| Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to cut in tread to cords (5.2.3 (d) (i)) | o reach the ply or cords has |
| MOT #8 | 2019-07-11 15:03 |
| MOT test number | 844509929558 |
| Result | ✓ Passed |
| Advice Oil leak, but not excessive (8.4.1 (a) (i)) | |
| Advice Offside Front lower arm ball joint dust cover split but is still stopping the | e ingress of dirt |
| | |

| MOT #7 | 2019-07-10 11:32 | |
|--|-----------------------------|--|
| MOT test number | 320273297049 | |
| Result | × Failed | |
| Fail Offside Side repeater not working (4.4.1 (a) (ii)) | | |
| Advice Offside Front lower arm ball joint dust cover split but is still st | copping the ingress of dirt | |
| Advice Oil leak, but not excessive (8.4.1 (a) (i)) | | |
| Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) | | |

| МОТ #6 | 2018-07-20 10:51 |
|---|------------------|
| MOT test number | 173492472825 |
| Result | ✓ Passed |
| Advice Offside Front Seat belt slightly damaged (7.1.2 (b) (i)) | |





| MOT #5 | 2018-07-20 07:28 |
|--|-----------------------|
| MOT test number | 514874588839 |
| Result | 🗙 Failed |
| Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no ingress of dirt (6.1.7 (g) (ii)) | o longer prevents the |
| Fail Central Front Seat belt buckle not functioning as intended (7.1.2 (d)) | |
| Fail Nearside Registration plate lamp inoperative in the case of a single lamp or all lamp | amps (4.7.1 (b) (ii)) |
| Advice Auxiliary belt damaged | |
| Advice Offside Front Seat belt slightly damaged (7.1.2 (b) (i)) | |

| MOT #4 | 2017-08-01 14:44 |
|-----------------|------------------|
| MOT test number | 260917903115 |
| Result | ✓ Passed |

| MOT #3 | 2016-09-08 10:54 |
|---|----------------------|
| MOT test number | 994369626576 |
| Result | Passed |
| Advice Nearside Front Tyre worn close to the legal limit CLOSE TO LEGAL I (4.1.E.1) | LIMITS ON OUTER EDGE |

| MOT #2 | 2015-09-09 14:43 |
|------------------------------|------------------|
| MOT test number | 742849451969 |
| Result | ✓ Passed |
| Advice Damage to o/s/f wing. | |

| MOT #1 | 2015-09-09 11:36 |
|---|------------------|
| MOT test number | 669985068315 |
| Result | 🗙 Failed |
| Fail Nearside Front Seat belt locking mechanism does not secure or release (5.2.5a) | |
| Advice Damage to o/s/f wing. | |



Tax & MOT check

| ✓ Taxed Tax due: 1 June 2024 | ✓ MOT Expires: 31 May 2024 |
|---------------------------------------|-------------------------------------|
| Tax status | Valid until 1 June |
| Days left | 34 |
| MOT expiry date | 31 May 2024 |
| Full MOT history | <u>See MOT history</u> |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | н |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | | |
|----------|--|-------|
| Date | F | |
| Category | | ARME |
| Туре | | |
| Damage 2 | | AMPLE |
| | E E | |
| Date | | \$ |
| Category | AMP | |
| Туре | No. Contraction of the second se | |

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 |





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ************ | |
| ******** | |
| ******* | |
| ************ | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this FORD had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |



EU14FOF report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 17 |
| First mileage registration | 2014-07-01 |
| Last registration | 2023-06-01 |
| Complete history | <u>See info</u> |



| Registration #1 | 2014-07-01 | 29 mi |
|------------------|------------|------------|
| Registration #2 | 2015-09-09 | 13.018 mi |
| Registration #3 | 2015-09-09 | 13.018 mi |
| Registration #4 | 2016-09-08 | 24.073 mi |
| Registration #5 | 2017-08-01 | 32.246 mi |
| Registration #6 | 2018-07-20 | 40.791 mi |
| Registration #7 | 2018-07-20 | 40.791 mi |
| Registration #8 | 2019-07-10 | 48.691 mi |
| Registration #9 | 2019-07-11 | 48.962 mi |
| Registration #10 | | 11.777 est |
| Registration #11 | | 11.707 esi |
| Registration #12 | | 11.777 esi |
| Registration #13 | | 11.707 est |
| Registration #14 | | 11.777 est |
| Registration #15 | | 11.777 esi |
| Registration #16 | | 11.777 est |
| Registration #17 | | 11.777 esi |
| | | |





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| S0482 | |
| \$0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 84% |
| Children | 90% |
| Pedestrian | 48% |
| Safety systems | 71% |
| Overall rating | 76% |
| Video | see crash video |



| Dimensions & weight | |
|---------------------------------|--------------------|
| Width | 2290 mm |
| Height | 2020 mm |
| Length | 5339 mm |
| Kerb weight | 2100 kg |
| Max. allowed weight | 3100 kg |
| Additional information | |
| Fuel tank capacity | 80 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 9 |
| Engine number CarCheck.co.uk | DD26081 page 12/12 |