



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	I10 SE
Colour	Blue
Year of manufacture	2017
Top speed	96 mph
0 - 60 mph	14.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	65 BHP
Max. torque	95 Nm at 3.500 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	108 g/km
CO2 label	B





Internet history

Entry 3

Date	2021-10-26
Pictures	0
Listing price	View report

source: [heycar.co.uk](#)

Entry 2

Date	2021-10-25
Pictures	15
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-09-30
Pictures	0
Listing price	View report

source: [heycar.co.uk](#)

**MOT history**

MOT expiry date	2024-10-01
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	20
Total items failed	2

MOT #7 2023-09-28 10:04**MOT test number** 686247001246**Result** ✓ Passed**Next expiry date** 2024-10-01

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened disks pitted and corroded (1.1.14 (a) (ii))

MOT #6 2023-09-28 10:04**MOT test number** 907123777913**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened disks pitted and corroded (1.1.14 (a) (ii))
- Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))

**MOT #5**

2022-09-25 10:18

MOT test number

103157233889

Result

✓ Passed

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened HEAVILY CORRODED (1.1.14 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front DAY TIME LIGHT NOT WORKING

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened HEAVILY CORRODED (1.1.14 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4

2022-09-25 09:39

MOT test number

224442304526

Result

✗ Failed

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened HEAVILY CORRODED (1.1.14 (a) (ii))

MAJOR Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened HEAVILY CORRODED (1.1.14 (a) (ii))

MAJOR Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front DAY TIME LIGHT NOT WORKING

MOT #3

2021-10-02 08:19

MOT test number

472786530956

Result

✓ Passed

MOT #2

2020-11-26 17:00

MOT test number

629639622836

Result

✓ Passed



MOT #1	2020-11-26 15:58
MOT test number	922296454902
Result	✗ Failed
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
MAJOR	Nearside Rear Service brake excessively binding (1.2.1 (f))



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
1 October 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	1 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2017-12-22
Last registration	2023-09-28
Complete history	See info



Registration #1	2017-12-22	22 mi
Registration #2	2020-11-26	21.162 mi
Registration #3	2020-11-26	21.162 mi
Registration #4	2020-11-26	21.162 mi
Registration #5	2021-10-02	23.816 mi
Registration #6	2023-09-28	25.277 mi
Registration #7	2023-09-28	25.277 mi
Registration #8	2023-09-28	25.277 mi
Registration #9	2023-09-28	25.277 mi
Registration #10	2023-09-28	25.277 mi
Registration #11	2023-09-28	25.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	79%
Children	80%
Pedestrian	71%
Safety systems	56%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1660 mm
Height	1500 mm
Length	3665 mm
Wheel base	2385 mm
Kerb weight	933 kg
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G3LAHM275871