





report date: 2024-03-29

General information

Make	RENAULT
Model	GRAND SCENIC GR DYNAMIQUE TT BOSE PLUS ENERGY DCI S/S
Colour	Grey
Year of manufacture	2014
Top speed	112 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	81 kW / 110 HP / 110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	72.4 mpg
Consumption combined	68.9 mpg
CO2 emission	105 g/km
CO2 label	В



CarCheck.co.uk page 1/12



LG64HZL

report date: 2024-03-29

Internet history

Е	n	t	ry	1

Date	2021-02-04
Pictures	0
Listing price	View report

source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-10-02
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	22
Total items failed	7

MOT #10	2023-09-06 14:04	
MOT test number	393809609975	
Result	✓ Passed	
Next expiry date	2024-10-02	
Minor Front Drive shaft joint constant velocity boot severely deteriorated both (6.1.7 (g) (i))		
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		

MOT #9	2022-10-01 14:49
MOT test number	176659209874
Result	✓ Passed
MOT #8	2021-10-02 13:47


MOT #8		2021-10-02 13:47
MOT test	number	522336164400
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



LG64HZL

report date: 2024-03-29



MOT #6	2020-09-30 07:41	
MOT test number	264102941102	
Result	X Failed	
Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))		
Advice Offside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))		
Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))		
Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.3)	1.7 (g) (i))	

MOT #5	2019-09-06 14:19
MOT test number	531383784538
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #4	2019-09-06 11:32
MOT test number	577698489050
Result	X Failed
Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	

CarCheck.co.uk page 4/12



MOT #3 2018-10-03 11:45

MOT test number 566554437315

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Nail in tyre

MOT #2 2018-10-02 15:22

MOT test number 255822346357

Result X Failed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Reversing lamp inoperative (4.6.1 (a))

Advice Nearside Rear Nail in tyre

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #1 2017-10-03 07:56

MOT test number 297566470657

Result

Passed

Advice Both front tyres bald on edges

Advice Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	2 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-


CarCheck.co.uk page 6/12



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



LG64HZL

report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	NK SIZ
Plate since	
	Moro info

CarCheck.co.uk page 9/12



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-09-30
Last registration	2023-09-06
Complete history	See info



Registration #1	2014-09-30	9 mi
Registration #2	2017-10-03	76.080 mi
Registration #3	2018-10-02	101.100 mi
Registration #4	2018-10-03	101.100 mi
Registration #5	2019-09-06	119.825 mi
Registration #6	2019-09-06	119.825 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		71.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	91%
Children	76%
Pedestrian	42%
Safety systems	99%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1845 mm
Height	1672 mm
Length	4573 mm
Wheel base	2770 mm
Kerb weight	1516 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/1

Number of axles 2

Engine number D228382