



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA EXCLUSIVE 16V PICASSO E4
Colour	Blue
Year of manufacture	2006
Top speed	119 mph
0 - 60 mph	10.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	191 Nm at 4.100 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.6 mpg
Consumption extra urban	44.1 mpg
Consumption combined	32.8 mpg
CO2 emission	205 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-07-05
Pictures	17
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-12-06
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	21
Total items failed	11

MOT #21 2023-12-06 15:13**MOT test number** 525330796099**Result** ✓ Passed**Next expiry date** 2024-12-06**Advice** O s r shocker damp-**Advice** Inner and outer sills corroded and distorted-o/s/f tyre edges worn-rear axle corroded**MOT #20** 2023-12-04 13:14**MOT test number** 917203494841**Result** ✗ Failed**Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill holed (5.3.6 (a) (i))**Fail** Nearside Rear Brake cable damaged (1.1.15 (a))**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Nearside Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill holed (5.3.6 (a) (i))**Fail** Nearside Rear Brake pipe likely to become detached or damaged (1.1.11 (d) (ii))**Advice** Inner and outer sills corroded and distorted-o/s/f tyre edges worn-rear axle corroded

**MOT #19**

2022-12-05 14:13

MOT test number

710763166421

Result

✓ Passed

Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))**Minor** Nearside Rear Brake hose slightly damaged (1.1.12 (b) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #18**

2022-12-05 14:13

MOT test number

822615611198

Result

✗ Failed

Pass with rectification Offside Rear Position lamp not working (4.2.1 (a) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Minor** Nearside Rear Brake hose slightly damaged (1.1.12 (b) (i))**MOT #17**

2021-11-24 07:47

MOT test number

885650133131

Result

✓ Passed

MOT #16

2020-12-07 15:39

MOT test number

108224823312

Result

✓ Passed

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #15** 2020-12-03 09:30**MOT test number** 197069956394**Result** ✗ Failed**Fail** Exhaust has a major leak of exhaust gases Centre exhaust broken/corroded (6.1.2 (a))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Emissions not tested (8.2.1.2 (d))**Fail** Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced O/S outer sill corroded and holed (6.1.1 (c) (i))**MOT #14** 2019-11-22 16:01**MOT test number** 585660964744**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #13** 2018-11-28 10:41**MOT test number** 378291920474**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2018-11-28 10:41**MOT test number** 315594494192**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2017-11-28 13:10**MOT test number** 236005454254**Result** ✓ Passed

**MOT #10** 2016-11-29 10:43**MOT test number** 623227476719**Result** ✓ Passed**MOT #9** 2016-11-28 12:15**MOT test number** 382233221228**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #8** 2016-02-13 09:46**MOT test number** 843513425827**Result** ✓ Passed**MOT #7** 2015-02-20 11:14**MOT test number** 156181255088**Result** ✓ Passed**MOT #6** 2014-02-18 09:51**MOT test number** 125749844071**Result** ✓ Passed**MOT #5** 2013-02-11 12:49**MOT test number** 968692243070**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2012-02-15 10:40**MOT test number** 939186442068**Result** ✓ Passed



MOT #3	2011-02-14 10:42
MOT test number	117555441456
Result	✓ Passed

MOT #2	2010-02-12 16:30
MOT test number	911093140077
Result	✓ Passed

MOT #1	2009-10-06 15:04
MOT test number	800759879212
Result	✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
6 December 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	6 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-09-29
Last registration	2023-12-06
Complete history	See info



Registration #1	2006-09-29	19 mi
Registration #2	2009-10-06	24.639 mi
Registration #3	2010-02-12	24.830 mi
Registration #4	2011-02-14	30.314 mi
Registration #5	2012-02-15	36.440 mi
Registration #6	2013-02-11	42.750 mi
Registration #7	2014-02-18	47.498 mi
Registration #8	2015-02-20	53.685 mi
Registration #9	2016-02-13	58.974 mi
Registration #10	2016-11-28	61.452 mi
Registration #11	2016-11-29	61.452 mi
Registration #12	2017-11-28	71.601 mi
Registration #13	2018-05-29	75.377 mi
Registration #14	2018-05-29	75.377 mi
Registration #15	2018-05-29	75.377 mi
Registration #16	2018-05-29	75.377 mi
Registration #17	2018-05-29	75.377 mi
Registration #18	2018-05-29	75.377 mi
Registration #19	2018-05-29	75.377 mi
Registration #20	2018-05-29	75.377 mi
Registration #21	2018-05-29	75.377 mi
Registration #22	2018-05-29	75.377 mi
Registration #23	2018-05-29	75.377 mi

More info >



Safety ratings

NCAP rating

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1245 kg
Max. allowed weight	1832 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LH4G1454817