





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT EXECUTIVE TDI BLUEMOTION TECHN
Colour	Grey
Year of manufacture	2014
Top speed	132 mph
0 - 100 km/h	10.0 seconds
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	120 g/km
CO2 label	С



CarCheck.co.uk page 1/12




Internet history

Entry 1

Date 2021-07-07

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-02-26
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	22
Total items failed	2

MOT #9	2024-02-12 17:07
MOT test number	770367661140
Result	✓ Passed
Next expiry date	2025-02-26
Advice Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))	

MOT #8		2023-02-27 13:51
MOT test	number	248643357273
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7		2023-02-25 12:46
MOT test	number	175194300598
Result		× Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))		
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2022-01-26 10:11 **MOT** test number 848320234897 Result × Failed Pass with rectification Offside Front Headlamp aim too low (4.1.2 (a)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Pass with rectification Nearside Front Headlamp aim too low (4.1.2 (a)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4

MOT test number

2021-01-28 12:30

Result

Advice (i))

Front Suspension arm pin or bush worn but not resulting in excessive movement o/s/n/s (5.3.4 (a)

 MOT #3
 2019-02-04 15:43

 MOT test number
 283268387955

 Result
 ✓ Passed

CarCheck.co.uk page 4/12




MOT test number

Result

Advice Rear number plate deteriorating

Advice Rear tyres worn inner edges and to wear indicators

Advice Wipers poor



CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	26 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.


Damage 1

Date	
Category	
Туре	
Damage 2	

Date

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



More info >

Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Downere.	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK SIK
Plate since	
Current registration	NK SIK
Plate since	

CarCheck.co.uk page 9/12



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-07-28
Last registration	2024-02-12
Complete history	See info



Registration #1	2014-07-28	19 mi
Registration #2	2017-06-13	51.437 mi
Registration #3	2018-05-04	66.485 mi
Registration #4	2019-02-04	75.079 mi
Registration #5	2021-01-28	91.873 mi
Registration #6		11.777 es
Registration #7		11.777 esi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1516 mm
Length	4771 mm
Wheel base	2712 mm
Kerb weight	1471 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
CarChaeleeaule	naga 12/12

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	CFFBK74752