





report date: 2024-03-28

General information

Make	LAND ROVER
Model	RANGE ROVER SPORT V8 S/C
Colour	Black
Year of manufacture	2006
Top speed	140 mph
0 - 60 mph	7.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	385 BHP
Max. torque	550 Nm at 3.500 rpm
Engine capacity	4.197 cc
Cylinders	8
Fuel type	Petrol
Consumption city	12.6 mpg
Consumption extra urban	23.2 mpg
Consumption combined	17.7 mpg
CO2 emission	374 g/km
CO2 label	М



CarCheck.co.uk page 1/12



LV06AYW report date: 2024-03-28

MOT history

MOT expiry date	2024-04-20
MOT pass rate	94 %
MOT passed	15
Failed MOT tests	1
Total advice items	32
Total items failed	1

MOT #16		2023-04-21 14:06
MOT test	number	434166386353
Result		✓ Passed
Next exp	ry date	2024-04-20
Advice	Offside Front Brake pipe corroded, covered in grease or other material to rea	r (1.1.11 (c))
Advice	The vehicles chassis and suspension components have surface corrosion	
Advice	Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
Advice	Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))	
Advice	Nearside Front Brake pipe corroded, covered in grease or other material to re	ear (1.1.11 (c))
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated	d (5.3.4 (b) (i))
Advice	Offside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
Advice	Brake hose has slight corrosion to ferrule all (1.1.12 (f) (i))	
Advice	Offside Front Tyre slightly damaged (5.2.3 (d) (ii))	

CarCheck.co.uk page 2/12



LV06AYW report date: 2024-03-28

MOT #15 2021-12-11 09:06

MOT test number 432345112595

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement lower arm rear bush (5.3.4 (a) (i))

Advice Nearside Rear Nail in tyre

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material front to rear pipe corroded (1.1.11 (c))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement lower arm rear bush (5.3.4 (a) (i))

Minor Offside Headlamp reflector slightly defective (4.1.1 (b) (i))

Advice Rear active anti-roll bar housing has light misting of oil

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing perished and worn on edges of tread (5.2.3 (d) (ii))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material front to rear pipe corroded (1.1.11 (c))

MOT #14 2020-11-11 12:51

MOT test number 474986850221

Result \(\sqrt{Passed} \)

Advice O/s headlight dim

Advice Rear brake pipes rusty

MOT #13 2019-09-07 09:46

MOT test number 391207365147

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #12		2018-09-10 09:15
MOT test	number	889523437470
Result		✓ Passed
MOT #11		2017-08-21 08:58
MOT test	number	861092620190
Result		✓ Passed
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Engine management light was on during test	
MOT #10		2016-08-24 12:36
MOTher		202606622001

Advice Engine management light was on during test	
MOT #10	2016-08-24 12:36
MOT test number	202696632901
Result	✓ Passed
MOT #9	2015-05-28 14:01
MOT test number	639958445153
Result	✓ Passed
MOT #8	2014-05-07 16:01
MOT test number	299097924489
Result	✓ Passed
MOT #7	2013-04-27 11:57
MOT test number	537077813153
Result	✓ Passed
MOT #6	2012-04-10 12:04
MOT test number	245661802440
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5

MOT test number

108749582077

Result

X Failed

Fail Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice O/s rear tyre sidewall damaged

MOT #4 2011-05-20 09:57

MOT test number 199940141192

Result ✓ Passed

MOT #3 2010-11-23 12:14

MOT test number 483927020476

Result

✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #2 2009-11-24 14:24

MOT test number 493778229348

Result \(\sqrt{Passed} \)

Advice Nearside Inner Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Outer Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Outer Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2009-07-22 16:49

MOT test number 524523209248

Result

Passed

CarCheck.co.uk page 5/12



LV06AYW report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 December
Days left	216
MOT expiry date	20 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

_ _

Damage 2
Date

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



LV06AYW report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



furthe scinors

LV06AYW

report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this LAND ROVER had different number plates.

CarCheck.co.uk page 9/12



LV06AYW report date: 2024-03-28

Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2006-06-06
Last registration	2023-04-21
Complete history	See info



Registration #1	2006-06-06	24 mi
Registration #2	2009-07-22	30.848 mi
Registration #3	2009-11-24	34.514 mi
Registration #4	2010-11-23	43.639 mi
Registration #5	2011-05-20	46.183 mi
Registration #6	2012-03-29	53.752 mi
Registration #7	2012-04-10	53.986 mi
Registration #8	2013-04-27	81.512 mi
Registration #9	2014-05-07	97.472 mi
Registration #10		13.777 es
Registration #11		11.777 es
Registration #11 Registration #12		11.777 es
-		11.777 es 11.777 es 11.777 es
Registration #12		11.777 es 11.777 es 11.777 es
Registration #12 Registration #13		11.777 es 11.777 es 11.777 es 11.777 es
Registration #12 Registration #13 Registration #14		10,777-66 10,777-66 10,777-66 10,777-66 10,777-66

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2170 mm
Height	1812 mm
Length	4788 mm
Wheel base	2745 mm
Max. allowed weight	3125 kg

Additional information

Fuel tank capacity	88 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	260905B04302428PS

CarCheck.co.uk page 12/12