





report date: 2024-03-29

General information

Make	ТОУОТА
Model	IQ VVT-I IQ2
Colour	White
Year of manufacture	2012
Top speed	93 mph
0 - 60 mph	15.3 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	67 BHP
Max. torque	91 Nm at 4.800 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	58.9 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/12



Internet history


Entry 1

Date 2021-08-20

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-08-11
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	16
Total items failed	5

MOT #11		2023-07-28 14:31
MOT test	number	962524233859
Result		✓ Passed
Next expi	ry date	2024-08-11
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.	1.14 (a) (ii))

CarCheck.co.uk page 3/12



ET12NYD

report date: 2024-03-29

MOT #10 2023-07-22 08:23

MOT test number 385174182371

Result X Failed

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Horn sound not in accordance with requirements (7.7 (c))

Fail Offside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Nearside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #9 2022-07-23 08:15

MOT test number 483811398270

Result / Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing slightly cracking (5.2.3 (d) (ii))

MOT #8 2021-07-29 08:10

MOT test number 777628757040

Result \rightarrow Passed

MOT #7 2021-07-29 08:10

MOT test number 689972610327

Result × Failed

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

CarCheck.co.uk page 4/12



MOT #6 2020-08-12 11:12

MOT test number 899494658877

MOT #5 2019-04-25 12:25

MOT test number 454342240248

Result Passed

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #4 2018-04-19 12:49

MOT test number 272093347755

Result ✓ Passed

MOT #3 2017-04-20 12:45

MOT test number 194975221510

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #2 2016-04-28 13:18

MOT test number 790056656321

Advice Front number plate deteriated

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #1 2015-05-01 12:10

MOT test number 248621625116

Result ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	11 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when miscory	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes See in this check if this TOYOTA had different number plates.	
See in this eneck is this 1919 in that amerene names places	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-07-31
Last registration	2023-07-28
Complete history	See info



Registration #1	2012-07-31	13 mi
Registration #2	2015-05-01	17.704 mi
Registration #3	2016-04-28	28.069 mi
Registration #4	2017-04-20	39.232 mi
Registration #5	2018-04-19	50.202 mi
Registration #6	2019-04-25	61.672 mi
Registration #7	2020-08-12	72.434 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		11.777 es
Registration #13		10.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	91%
Children	71%
Pedestrian	54%
Safety systems	86%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1680 mm
Height	1500 mm
Length	2985 mm
Wheel base	2000 mm
Kerb weight	845 kg
Max. allowed weight	1215 kg

Additional information

Fuel tank capacity	32 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2

Engine number 1KR1343429