





report date: 2024-03-29

## General information

Make	RENAULT
Model	SCENIC I-MUSIC VVT
Colour	Blue
Year of manufacture	2010
Top speed	115 mph
0 - 100 km/h	11.7 seconds
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	81 kW / 110 HP / 109 BHP
Max. torque	151 Nm at 4.250 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	47.9 mpg
Consumption combined	38.2 mpg
CO2 emission	174 g/km
CO2 label	Н



CarCheck.co.uk page 1/12



report date: 2024-03-29

## Internet history

F	n	t	r۱	,	2
_				,	_

, -	
Date	2022-02-03
Pictures	0
Listing price	View report

#### source: autotrader.co.uk

#### Entry 1

Date	2022-01-26
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

## MOT history

MOT expiry date	2025-04-15
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	15
Total items failed	0

MOT #13	2024-04-16 13:46
MOT test number	298371311179
Result	<b>✓</b> Passed
Next expiry date	2025-04-15
Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Under tray fitted	
Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #12	2023-01-24 16:35
MOT test number	994055177540
Result	✓ Passed
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #11		2023-01-17 09:40
MOT test r	number	956163352868
Result		<b>×</b> Failed
MAJOR	Nearside Reversing lamp inoperative (4.6.1 (a))	
MAJOR the ingress	Nearside Front Outer Drive shaft joint constant velocity boot split or insect of dirt $(6.1.7 (g) (ii))$	ure, no longer prevents
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #10	2022-01-25 12:09

**MOT test number** 621575103716

MOT #9 2020-11-27 11:17

MOT test number 646777660027

Result 

Passed

MOT #8 2020-11-26 15:39

**MOT test number** 701471751368

**Result** X Failed

MAJOR Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #7** 2019-09-17 08:17

**MOT test number** 375450433062

**Result** ✓ Passed

**MOT #6** 2018-09-11 09:56

**MOT test number** 591125057829

Result \rightarrow Passed

MOT #5 2017-09-16 08:18

MOT test number 329070140550

Result \rightarrow Passed

**Advice** Nearside Front mirror glass cracked

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4		2016-10-01 08:39
MOT test	number	529907100098
Result		<b>✓</b> Passed
Advice	Nearside Front mirror glass cracked	
Advice	Offside Rear tyre pereshing	
Advice	Nearside Front tyre wearing on edge	

MOT #3	2015-10-19 08:44
MOT test number	192906629048
Result	<b>✓</b> Passed
Advice Nearside mirror damage	

MOT #2	2014-11-24 15:13
MOT test number	888018624331
Result	<b>✓</b> Passed
Notice N/s mirror cracked	

MOT #1	2013-11-25 12:06
MOT test number	526159523361
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

## Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	15 April 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

## Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
THE STATE OF THE S	
***************************************	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of sisters	
access of passing	
Current registration	NK NK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

## Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-11-30
Last registration	2024-04-16
Complete history	See info



Registration #1	2010-11-30	26 mi
Registration #2	2013-11-25	11.480 mi
Registration #3	2014-11-24	15.352 mi
Registration #4	2015-10-19	18.071 mi
Registration #5	2016-10-01	20.919 mi
Registration #6	2017-09-16	24.759 mi
Registration #7	2018-09-11	28.909 mi
Registration #8	2019-09-17	36.441 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.777 es

7070.70.70

More info >

77.777 86

CarCheck.co.uk page 11/12



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1486 mm
Height	1637 mm
Length	4344 mm
Wheel base	2703 mm
Kerb weight	1320 kg
Max. allowed weight	1877 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/

Number of axles2Engine numberD051923